



**CAUTION. DO NOT USE THIS CHART**  
 UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.  
**ATTENTION. NE PAS UTILISER CE TABLEAU**  
 SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.  
**PRECAUTION. NO USE ESTA TABLA**  
 A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

AC DELCO	AC DELCO	AC DELCO	AC DELCO	AC DELCO					
2	3025 / RV19PMC	41825	7318 / RC12PMPB4	41XLS	813 / N7YC	B403I	533 / UJ11G	FR3LM	412 / RC12LYC
4	3415 / RN9PYC	41825	7346 / RC10PYP4	426FS	312 / L87YC	B43	823 / J6C	FR3LS	71 / RC12YC
5	3071 / RC12PYC	41826	7018 / RV17PMP4	42F	811 / L82C	B44S	10 / J12YC	FR3LS6	89 / RC12YC5
6	3983 / RS14PMC85	41827	3405 / RN14PMC	42FS	328 / L82YC	B45	841 / J8C	FR3LSJ	71 / RC12YC
8	3401 / RS10PYC4	41829	430 / RC9YC4	42LTS	304 / RS9YC	BR42TS	406 / RV12YC	FR3LSK	71 / RC12YC
9	3071 / RC12PYC	41830	108 / RV8C6	42S	10 / J12YC	C421	825 / J4C	FR3LX	71 / RC12YC
14	3013 / RS14PYC6	41831	431 / RC14YC	42TS	406 / RV12YC	C42N	803 / N4C	FR4LE	412 / RC12LYC
14	597 / K97F	41832	123 / RN5C	42XL	801 / N3C	C43	823 / J6C	FR4LS	431 / RC14YC
16	597 / K97F	41900	7013 / RS14PYP5	42XLS	300 / N9YC	C43L	587 / H8C	FR4LSJ	431 / RC14YC
17	562 / W95D	41902	7013 / RS14PYP5	430Z	811 / L82C	C43N	120 / N5C	FR5LM	431 / RC14YC
18	589 / W89D	41904	7013 / RS14PYP5	436T	802 / V63C	C44	841 / J8C	FR5LS	431 / RC14YC
26	525 / 25	41905	18 / RV15YC4	436TS	672 / V59YC	C44N	120 / N5C	G53	595 / C95F
43	823 / J6C	41905	7018 / RV17PMP4	436XLS	796 / C63YC	C44NS	405 / RN14YC	G54	595 / C95F
44	841 / J8C	41906	7013 / RS14PYP5	438T	265 / V63Y	C44S	10 / J12YC	G56	525 / 25
45	841 / J8C	41907	7346 / RC10PYP4	438T	802 / V63C	C44XL	120 / N5C	G59	525 / 25
46	511 / J11C	41908	7020 / RS12PLP6	43FS	929 / RL95YC	C45L	844 / H10C	LM46	845 / J17LM
373	506 / D6	41910	7013 / RS14PYP5	43LS	91 / H14Y	C45W	843 / C/J8	LM49	846 / C/J14
373	509 / D9	41913	7346 / RC10PYP4	43N	120 / N5C	C47W	843 / C/J8	M40FFX	821 / L77JC4
404	620 / RL85G	41919	7963 / RS12PYPB5	43S	10 / J12YC	C49	592 / RJ12C	M41FF	821 / L77JC4
41100	9405 / RS14WMPB4	41921	7013 / RS14PYP5	43TS	18 / RV15YC4	C73	510 / W10	M41G	825 / J4C
41101	3013 / RS14PYC6	41921	7940 / RS14PYPB5	43XL	120 / N5C	C75	569 / W14	M41K	825 / J4C
41101	7940 / RS14PYPB5	41928	7020 / RS12PLP6	43XLS	38 / N12YC	C77	561 / W16Y	M42FF	811 / L82C
41101	9404 / RS14WYPB5	41929	7013 / RS14PYP5	440T	802 / V63C	C77L	518 / W18	M42K	825 / J4C
41103	7437 / RE10PYPB5	41931	7013 / RS14PYP5	440XLS	315 / N6YC	C81	529 / D14N	M43FF	306 / L86C
41103	9901 / RE10WYPB5	41932	7940 / RS14PYPB5	445Z	807 / L78C	C82	509 / D9	M43S	10 / J12YC
41105	7437 / RE10PYPB5	41933	7940 / RS14PYPB5	44F	896 / L90C	C83	509 / D9	M44C	841 / J8C
41105	9901 / RE10WYPB5	41936	7013 / RS14PYP5	44FFS	929 / RL95YC	C83T	129 / RF10C	M44L	844 / H10C
41107	9901 / RE10WYPB5	41937	7940 / RS14PYPB5	44N	120 / N5C	C84T	129 / RF10C	M45	841 / J8C
41108	9300 / RE12WYBP4	41940	7940 / RS14PYPB5	44NS	405 / RN14YC	C85	514 / D14	M45FF	896 / L90C
41109	9299 / RES8WYBP4	41942	7013 / RS14PYP5	44S	10 / J12YC	C85S	526 / RD15Y	M47	592 / RJ12C
41110	9405 / RS14WMPB4	41943	7013 / RS14PYP5	44T	113 / RV12C	C85TS	21 / RF14YC	M8	842 / UY6
41600	13 / RS14YC6	41943	7940 / RS14PYPB5	44TS	25 / RV17YC	C86	514 / D14	MB42K	825 / J4C
41600	408 / RS14YC	41947	7013 / RS14PYP5	44XL	120 / N5C	C86	529 / D14N	MR4IT	802 / V63C
41601	13 / RS14YC6	41948	7940 / RS14PYPB5	44XLO	405 / RN14YC	C86S	549 / D18Y	MR42FF	874 / RL82C
41602	71 / RC12YC	41950	7940 / RS14PYPB5	44XLS	405 / RN14YC	C87	516 / D16	MR43FF	830 / RL86C
41603	431 / RC14YC	41952	7983 / RS14PMPB5	45F	896 / L90C	C88	502 / D21	MR43LTS	401 / RS12YC
41604	130 / RF14LC	41955	7981 / RE14PYPB4	45FFS	929 / RL95YC	C88L	523 / D23	MR43T	121 / RV8C
41605	31 / RN14MC5	41963	7963 / RS12PYPB5	45L	844 / H10C	CR42N	104 / RN4C	MR44C	871 / RJ8C
41606	13 / RS14YC6	41965	7981 / RE14PYPB4	45LS	857 / RH18Y	CR42TS	406 / RV12YC	MR44T	113 / RV12C
41608	89 / RC12YC5	41974	7983 / RS14PMPB5	45NS	405 / RN14YC	CR43	102 / RJ6C	MR45	871 / RJ8C
41610	71 / RC12YC	41975	7940 / RS14PYPB5	45S	58 / RJ18YC	CR43K	102 / RJ6C	R121XLS	809 / RA6HC
41611	89 / RC12YC5	41978	7940 / RS14PYPB5	45TS	25 / RV17YC	CR43L	587 / H8C	R40TS	400 / RV9YC
41617	71 / RC12YC	41979	7940 / RS14PYPB5	45XL	120 / N5C	CR43N	123 / RN5C	R41CF	807 / L78C
41618	431 / RC14YC	41980	7940 / RS14PYPB5	45XLS	405 / RN14YC	CR43S	14 / RJ12YC	R41CXL	818 / RN2C
41627	71 / RC12YC	41981	7981 / RE14PYPB4	46F	896 / L90C	CR43TS	18 / RV15YC4	R41CXLS	332 / RN7YC
41628	71 / RC12YC	41983	7983 / RS14PMPB5	46FFS	929 / RL95YC	CR43TSM	18 / RV15YC4	R41F	883 / QL78C
41629	431 / RC14YC	41983	9405 / RS14WMPB4	46N	120 / N5C	CR44N	123 / RN5C	R41T	802 / V63C
41630	89 / RC12YC5	41984	7940 / RS14PYPB5	46S	58 / RJ18YC	CR44NS	405 / RN14YC	R41TS	400 / RV9YC
41800	7071 / RC12PYP	41985	7983 / RS14PMPB5	46TS	25 / RV17YC	CR44TS	25 / RV17YC	R41XL	818 / RN2C
41801	7071 / RC12PYP	41985	9405 / RS14WMPB4	46XL	120 / N5C	CR45L	854 / RH10C	R41XLS	332 / RN7YC
41801	7546 / RC10PYPB4	41986	7940 / RS14PYPB5	46XLS	405 / RN14YC	CR45TS	25 / RV17YC	R42CF	874 / RL82C
41803	7018 / RV17PMP4	41987	7963 / RS12PYPB5	47XL	120 / N5C	CR82	509 / D9	R42CFS	814 / RL82YC
41804	3415 / RN9PYC	41988	7437 / RE10PYPB5	60G	191 / CH238	CR83	509 / D9	R42CLTS	401 / RS12YC
41805	7015 / RS14PMP4	41990	9901 / RE10WYPB5	61G	143	CR83T	129 / RF10C	R42CLTS6	13 / RS14YC6
41806	7071 / RC12PYP	41991	7304 / RS9PYP	62G	144	CS40	849 / C/J6	R42CT	121 / RV8C
41807	7071 / RC12PYP	41991	9808 / RS8WYPB5	700Y	580 / W80N	CS41	843 / C/J8	R42CTS	406 / RV12YC
41807	7712 / QC12PEP	41993	7940 / RS14PYPB5	700YX	580 / W80N	CS41T	851 / DJ6J	R42CXL	104 / RN4C
41810	7401 / RS12PYP5	16L	597 / K97F	701Y	545 / W85N	CS42	845 / J17LM	R42CXLS	415 / RN9YC
41810	7963 / RS12PYPB5	18A	543 / D89D	78S	520 / W20	CS42S	853 / C/J7Y	R42F	874 / RL82C
41811	7407 / RS14ZPYPB	28G	160 / CH60	800LY	542 / B86N	CS42T	850 / DJ7J	R42FS	814 / RL82YC
41813	7332 / RN10PYP4	29G	161 / CH61	83TS	409 / RF9YC	CS44TA	847 / DJ8J	R42LTS	401 / RS12YC
41814	7437 / RE10PYPB5	30G	168 / CH68	84T	129 / RF10C	CS45	843 / C/J8	R42LTS6	13 / RS14YC6
41815	7071 / RC12PYP	32G	184 / CH84	84TS	22 / RF11YC	CS45T	847 / DJ8J	R42LTSM	15 / RS15LYC
41816	7018 / RV17PMP4	40TS	400 / RV9YC	85T	129 / RF10C	CS49	846 / C/J14	R42S	14 / RJ12YC
41817	7018 / RV17PMP4	40XLS	315 / N6YC	85TS	21 / RF14YC	FR1LS	430 / RC9YC4	R42T	121 / RV8C
41819	7031 / RN14PMP5	41F	807 / L78C	86TS	11 / RF18YC	FR2LS	71 / RC12YC	R42TS	406 / RV12YC
41822	7407 / RS14ZPYPB	41TS	400 / RV9YC	87TS	21 / RF14YC	FR2LSK	71 / RC12YC	R42TSM	406 / RV12YC
41824	7407 / RS14ZPYPB	41XL	805 / N2C	8G	180 / CH80	FR3CLS	71 / RC12YC	R42TSX	79 / RV15YC6



**CAUTION. DO NOT USE THIS CHART**

UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.

**ATTENTION. NE PAS UTILISER CE TABLEAU**

SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.

**PRECAUCIÓN. NO USE ESTA TABLA**

A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

AC DELCO		AC DELCO		AC DELCO		ACCEL		ACCEL			
R42TX	108 / RV8C6	R45NSX	105 / RN16YC5	S42FR	811 / L82C	141	895 / QN84	784	345 / RC8YC4		
R42XL	880 / RN3C	R45NTSE	407 / RS14LC	S42XL	801 / N3C	142	673 / N59DR	784	346 / RC10YC4		
R42XLS	415 / RN9YC	R45S	58 / RJ18YC	S42XLR	880 / RN3C	142	801 / N3C	784	418 / RC9YCN4		
R42XLS6	415 / RN9YC	R45SX	66 / RJ18YC6	S438XLG	689 / C53R	142	810 / RA8HC	784	426 / RC9YC5		
R42XLSM	101 / RN13LYC	R45T	113 / RV12C	S438XLS	315 / N6YC	142	880 / RN3C	784	430 / RC9YC4		
R43	102 / RJ6C	R45TS	25 / RV17YC	S43XL	120 / N5C	142	915 / QN86	784	434 / RC9MC4		
R43C	102 / RJ6C	R45TS6	37 / RV17YC6	S43XLR	123 / RN5C	143	104 / RN4C	786	436 / RC12LC4		
R43CFS	929 / RL95YC	R45TS8	17 / RV19YC6	S44	841 / J8C	143	120 / N5C	786	71 / RC12YC		
R43CS	14 / RJ12YC	R45TS8	37 / RV17YC6	S44F	896 / L90C	143	123 / RN5C	786	7346 / RC10PPY4		
R43CT	121 / RV8C	R45TSX	17 / RV19YC6	S44XL	120 / N5C	143	803 / N4C	786	89 / RC12YC5		
R43CT6	108 / RV8C6	R45TSX	37 / RV17YC6	S45F	896 / L90C	146	120 / N5C	842	810 / RA8HC		
R43CTS	18 / RV15YC4	R45T	35 / RV12C6	S82F	509 / D9	154	811 / L82C	882	809 / RA6HC		
R43CTS6	79 / RV15YC6	R45XL	123 / RN5C	S83F	509 / D9	156	306 / L86C	882	810 / RA8HC		
R43CXL	123 / RN5C	R45XLS	405 / RN14YC	S85F	514 / D14	166	587 / H8C	997	101 / RN13LYC		
R43CXLS	322 / RN11YC4	R45XLS6	105 / RN16YC5	SB41	825 / J4C	168	512 / H12	276S	18 / RV15YC4		
R43FS	929 / RL95YC	R46	511 / J11C	SR43E	557 / XEJ8	168	844 / H10C	437S	63 / RJ14YC		
R43L	587 / H8C	R46LTS	408 / RS14YC	SR43LE	610 / REL88B	194	415 / RN9YC	574S	406 / RV12YC		
R43LTS	401 / RS12YC	R46N	120 / N5C	SR44E	557 / XEJ8	196	322 / RN11YC4	576S	18 / RV15YC4		
R43LTS6	15 / RS15LYC	R46S	58 / RJ18YC	SR45LE	610 / REL88B	198	66 / RJ18YC6	P526S	15 / RS15LYC		
R43LTSM	403 / RS10LC	R46SX	58 / RJ18YC	SR46E	567 / XEJ12	261	668 / V55C	P526S	401 / RS12YC		
R43LTSX	401 / RS12YC	R46SX	66 / RJ18YC6	SR47E	567 / XEJ12	262	669 / V57C	UR6	400 / RV9YC		
R43NTS6	13 / RS14YC6	R46SZ	58 / RJ18YC	SR47LE	610 / REL88B	263	670 / V59C	<b>ALLIS-CHALMERS</b>			
R43NTSE	403 / RS10LC	R46SZ	66 / RJ18YC6	SR47XL	614 / XEN14	265	802 / V63C	4905797	120 / N5C		
R43S	14 / RJ12YC	R46T	113 / RV12C	SR84E	572 / XED14	272	672 / V59YC	4905800	516 / D16		
R43T	121 / RV8C	R46TS	19 / RV19YC	SR86E	563 / XED16	274	400 / RV9YC	4907335	841 / J8C		
R43T6	108 / RV8C6	R46TSX	17 / RV19YC6	SV4XL	890 / N19V	274	406 / RV12YC	74905796	120 / N5C		
R43TS	18 / RV15YC4	R46TX	35 / RV12C6	SVB4XL	890 / N19V	276	18 / RV15YC4	74905798	120 / N5C		
R43TS6	79 / RV15YC6	R46XL	120 / N5C	V400S	825 / J4C	286	79 / RV15YC6	74905800	516 / D16		
R43TSK	18 / RV15YC4	R46XLS	405 / RN14YC	V40FFK	833	375	409 / RF9YC	79001651	120 / N5C		
R43TSX	79 / RV15YC6	R47S	58 / RJ18YC	V40FFM	827	378	22 / RF11YC	79001652	823 / J6C		
R43TX	108 / RV8C6	R47SX	66 / RJ18YC6	V40FFS	833	416	71 / RC12YC	<b>ARCTIC CAT</b>			
R43XL	123 / RN5C	R800	519 / RM77N	V40K	825 / J4C	437	14 / RJ12YC	217727	977 / RG6YC		
R43XLS	404 / RN12YC	R83CT	129 / RF10C	VB40FFM	831 / UL77V	437	63 / RJ14YC	217799	977 / RG6YC		
R44	871 / RJ8C	R83CTS	409 / RF9YC	VR40FFK	838	442	880 / RN3C	<b>AUDI</b>			
R44CF	896 / L90C	R83T	129 / RF10C	VR40FFM	898 / QL76V	453	814 / RL82YC	101905616	353 / RC89TMC		
R44CXL	123 / RN5C	R83TS	409 / RF9YC	WR43	588 / XMJ14	494	301 / RN9YC4	101905606A	9702 / KATZWYP84		
R44CXLS	405 / RN14YC	R84TS	22 / RF11YC	WR43L	603 / XML12	494	415 / RN9YC	<b>AUTOLITE</b>			
R44F	896 / L90C	R84TSX	22 / RF11YC	WR43LR	612 / RML12	494	7332 / RN10PPY4	12	400 / RV9YC		
R44LT	304 / RS9YC	R85T	129 / RF10C	WR44	588 / XMJ14	496	308 / RN12MC4	12	400 / RV9YC		
R44LTS	408 / RS14YC	R85TS	21 / RF14YC	WR44LS	633 / XML15Y	496	322 / RN11YC4	13	400 / RV9YC		
R44LTS6	13 / RS14YC6	R86T	129 / RF10C	WR46	517 / XMJ17	496	404 / RN12YC	14	406 / RV12YC		
R44LTS6K	13 / RS14YC6	R86TS	11 / RF18YC	WR47	588 / XMJ14	496	7031 / RN14PMP5	15	406 / RV12YC		
R44LTSM	15 / RS15LYC	R86TS5	11 / RF18YC	WR84	649 / XMD15	498	66 / RJ18YC6	16	18 / RV15YC4		
R44LTSM6	15 / RS15LYC	S102F	808 / Z9Y	WR86	521 / XMD21	504	403 / RS10LC	23	400 / RV9YC		
R44LTSMA	15 / RS15LYC	S104F	808 / Z9Y	WR87	521 / XMD21	506	407 / RS14LC	24	406 / RV12YC		
R44LTSMA	20 / RS13LYC5	S121F	816 / P7	<b>ACCEL</b>				514	304 / RS9YC	25	18 / RV15YC4
R44N	123 / RN5C	S121XL	809 / RA6HC	111	904 / RN4YC	514	403 / RS10LC	26	18 / RV15YC4		
R44NS	405 / RN14YC	S122F	816 / P7	112	315 / N6YC	516	408 / RS14YC	27	25 / RF11YC		
R44NTSE	407 / RS14LC	S123XL	810 / RA8HC	113	332 / RN7YC	526	15 / RS15LYC	32	409 / RF9YC		
R44S	14 / RJ12YC	S124FS	888 / P8Y	113	813 / N7YC	526	401 / RS12YC	33	409 / RF9YC		
R44SX	66 / RJ18YC6	S404XLG	690 / C57R	114	300 / N9YC	566	113 / RV12C	34	409 / RF9YC		
R44T	113 / RV12C	S408XLG	696 / C59R	115	300 / N9YC	566	35 / RV12C6	35	22 / RF11YC		
R44TS	25 / RV17YC	S40F	811 / L82C	116	302 / N11YC	574	406 / RV12YC	36	22 / RF11YC		
R44TS6	37 / RV17YC6	S40FR	883 / QL78C	116	38 / N12YC	576	18 / RV15YC4	37	21 / RF14YC		
R44TS8	37 / RV17YC6	S40XL	686 / C57	117	105 / RN16YC5	577	25 / RV17YC	44	409 / RF9YC		
R44TSX	37 / RV17YC6	S40XLG	687 / C59	117	31 / RN14MC5	577	37 / RV17YC6	45	22 / RF11YC		
R44TX	35 / RV12C6	S40XLR	686 / C57	117	405 / RN14YC	586	18 / RV15YC4	46	22 / RF11YC		
R44XL	123 / RN5C	S41F	807 / L78C	123	825 / J4C	586	79 / RV15YC6	51	315 / N6YC		
R44XLS	405 / RN14YC	S41FR	807 / L78C	124	102 / RJ6C	596	79 / RV15YC6	52	813 / N7YC		
R44XLS5	105 / RN16YC5	S41XL	805 / N2C	124	823 / J6C	675	409 / RF9YC	53	300 / N9YC		
R44XLS6	105 / RN16YC5	S41XLG	688 / C61	124	841 / J8C	736	412 / RC12LYC	54	302 / N11YC		
R44XLS6	105 / RN16YC5	S41XLR	818 / RN2C	124	871 / RJ8C	736	82 / RFN14LY	55	38 / N12YC		
R44XLSM	101 / RN13LYC	S42	825 / J4C	134	10 / J12YC	742	810 / RA8HC	56	405 / RN14YC		
R45	871 / RJ8C	S420Z	896 / L90C	137	10 / J12YC	761	791 / C57YC	57	405 / RN14YC		
R45LS	854 / RH10C	S42ZZ	896 / L90C	138	58 / RJ18YC	762	792 / C59YC	62	332 / RN7YC		
R45LTS6	13 / RS14YC6	S42S	306 / L86C	141	723 / N57DR	763	794 / C61YC	63	415 / RN9YC		
R45LTS6K	13 / RS14YC6	S426FS	312 / L87YC	141	805 / N2C	765	796 / C63YC	64	322 / RN11YC4		
R45NS	405 / RN14YC	S42F	811 / L82C	141	818 / RN2C	784	344 / RC9YC	65	404 / RN12YC		



**CAUTION. DO NOT USE THIS CHART**  
 UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.  
**ATTENTION. NE PAS UTILISER CE TABLEAU**  
 SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.  
**PRECAUTION. NO USE ESTA TABLA**  
 A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

AUTOLITE		AUTOLITE		AUTOLITE		AUTOLITE		AUTOLITE	
66	405 / RN14YC	316	511 / J11C	685	108 / RV8C6	2592	687 / C59	3924	71 / RC12YC
67	405 / RN14YC	317	511 / J11C	687	35 / RV12C6	2593	688 / C61	3926	431 / RC14YC
72	10 / J12YC	318	592 / RJ2C	704	400 / RV9YC	2594	801 / N3C	3927	431 / RC14YC
73	10 / J12YC	344	129 / RF10C	724	400 / RV9YC	2611	686 / C57	3954	810 / RA8HC
74	10 / J12YC	353	825 / J4C	725	406 / RV12YC	2612	805 / N2C	3964	810 / RA8HC
75	10 / J12YC	354	823 / J6C	726	18 / RV15YC4	2614	805 / N2C	4051	805 / N2C
76	58 / RJ18YC	355	841 / J8C	745	409 / RF9YC	2615	803 / N4C	4053	805 / N2C
77	58 / RJ18YC	356	841 / J8C	746	22 / RF11YC	2616	120 / N5C	4054	805 / N2C
84	14 / RJ12YC	357	511 / J11C	747	21 / RF14YC	2634	821 / L77JC4	4055	801 / N3C
85	14 / RJ12YC	358	592 / RJ12C	764	401 / RS12YC	2635	807 / L78C	4056	803 / N4C
86	58 / RJ18YC	363	102 / RJ6C	765	401 / RS12YC	2636	811 / L82C	4092	807 / L78C
87	58 / RJ18YC	372	506 / D6	766	408 / RS14YC	2652	807 / L78C	4093	811 / L82C
94	304 / RS9YC	373	509 / D9	767	408 / RS14YC	2653	807 / L78C	4113	328 / L82YC
103	304 / RS9YC	374	509 / D9	784	129 / RF10C	2654	811 / L82C	4114	312 / L87YC
104	401 / RS12YC	375	514 / D14	804	129 / RF10C	2655	811 / L82C	4123	814 / RL82YC
105	401 / RS12YC	376	516 / D16	824	106 / RZF10	2656	306 / L86C	4132	905 / RA4HC
113	129 / RF10C	377	502 / D21	847	66 / RJ18YC6	2675	587 / H8C	4133	809 / RA6HC
115	129 / RF10C	378	523 / D23	865	401 / RS12YC	2676	844 / H10C	4143	809 / RA6HC
117	129 / RF10C	379	543 / D89D	884	13 / RS14YC6	2677	844 / H10C	4152	905 / RA4HC
124	129 / RF10C	386	541 / RD16	893	300 / N9YC	2693	506 / D6	4153	809 / RA6HC
125	130 / RF14LC	388	502 / D21	912	101 / RN13LYC	2695	506 / D6	4162	905 / RA4HC
127	129 / RF10C	393	801 / N3C	915	101 / RN13LYC	2696	509 / D9	4163	809 / RA6HC
131	668 / V55C	394	120 / N5C	922	101 / RN13LYC	2697	514 / D14	4164	810 / RA8HC
132	669 / V57C	395	120 / N5C	925	101 / RN13LYC	2714	816 / P7	4194	808 / Z9Y
133	670 / V59C	396	120 / N5C	935	412 / RC12LYC	2715	816 / P7	4251	315 / N6YC
134	802 / V63C	397	120 / N5C	945	101 / RN13LYC	2716	888 / P8Y	4252	813 / N7YC
135	802 / V63C	398	504 / N21	965	406 / RV12YC	2735	888 / P8Y	4253	300 / N9YC
136	121 / RV8C	402	818 / RN2C	966	37 / RV17YC6	2744	308 / RN12MC4	4263	415 / RN9YC
143	802 / V63C	403	880 / RN3C	985	412 / RC12LYC	2755	809 / RA6HC	4265	404 / RN12YC
144	121 / RV8C	404	104 / RN4C	1101	160 / CH60	2772	509 / D9	4275	10 / J12YC
145	121 / RV8C	405	123 / RN5C	1102	161 / CH61	2773	509 / D9	4316	844 / H10C
146	113 / RV12C	406	123 / RN5C	1103	168 / CH68	2775	516 / D16	4345	101 / RN13LYC
147	113 / RV12C	411	807 / L78C	1104	169 / CH69	2794	889 / Z6	5125	130 / RF14LC
156	22 / RF11YC	413	811 / L82C	1107	180 / CH80	2795	808 / Z9Y	5143	403 / RS10LC
166	22 / RF11YC	414	306 / L86C	1108	184 / CH84	2796	808 / Z9Y	5144	407 / RS14LC
175	10 / J12YC	415	306 / L86C	1111	190 / CH237	2812	825 / J4C	5164	15 / RS15LYC
203	406 / RV12YC	416	896 / L90C	1118	193 / CH218	2832	506 / D6	5184	89 / RC12YC5
215	844 / H10C	425	830 / RL86C	2222	572 / XED14	2852	827	5224	71 / RC12YC
216	844 / H10C	426	896 / L90C	2223	649 / XMD15	2872	833	5243	15 / RS15LYC
217	844 / H10C	436	91 / H14Y	2224	521 / XMD21	2892	831 / UL77V	5245	15 / RS15LYC
218	512 / H12	437	857 / RH18Y	2225	563 / XED16	2932	890 / N19V	AP103	7304 / RSSPYP
225	854 / RH10C	447	857 / RH18Y	2226	521 / XMD21	2954	850 / DJ7J	AP104	3401 / RS10PYC4
227	854 / RH10C	456	845 / J17LM	2227	521 / XMD21	2956	847 / DJ8J	AP105	3013 / RS14PYC5
235	843 / CJ8	458	861 / J19LM	2242	557 / XEJ8	2974	858 / CJ6Y	AP106	3408 / RS10PYC
245	840 / RCJ8	483	304 / RS9YC	2243	588 / XMJ14	2976	848 / CJ8Y	AP24	3018 / RV17PMC4
253	862 / CJ4	494	587 / H8C	2244	557 / XEJ8	2984	852 / RCJ6Y	AP25	3018 / RV17PMC4
254	849 / CJ6	495	587 / H8C	2245	517 / XMJ17	2985	859 / RCJ7Y	AP2543	3407 / RS14ZPYC5
255	843 / CJ8	497	844 / H10C	2246	567 / XEJ12	2995	843 / CJ8	AP2544	3407 / RS14ZPYC5
258	846 / CJ14	515	929 / RL95YC	2247	573 / XMJ20	2996	843 / CJ8	AP2545	3407 / RS14ZPYC5
273	328 / L82YC	516	929 / RL95YC	2248	567 / XEJ12	3013	825 / J4C	AP2546	3407 / RS14ZPYC5
274	312 / L87YC	517	929 / RL95YC	2285	610 / REL88B	3014	823 / J6C	AP26	3018 / RV17PMC4
275	929 / RL95YC	535	306 / L86C	2304	616 / XMN12	3017	592 / RJ12C	AP3923	3071 / RC12PYC
276	896 / L90C	536	896 / L90C	2305	616 / XMN12	3035	555 / UD16	AP3923	3346 / RC10PYC
284	327 / RL87YC	565	66 / RJ18YC6	2307	614 / XEN14	3055	129 / RF10C	AP3924	3071 / RC12PYC
292	825 / J4C	566	66 / RJ18YC6	2325	610 / REL88B	3064	129 / RF10C	AP5143	3407 / RS14ZPYC5
294	841 / J8C	567	66 / RJ18YC6	2326	610 / REL88B	3074	510 / W10	AP5144	3407 / RS14ZPYC5
295	841 / J8C	584	129 / RF10C	2327	610 / REL88B	3075	569 / W14	AP5184	3071 / RC12PYC
297	511 / J11C	603	13 / RS14YC6	2344	612 / RML12	3076	569 / W14	AP5224	3071 / RC12PYC
298	511 / J11C	604	13 / RS14YC6	2384	603 / XML12	3077	589 / W89D	AP5245	3015 / RS14PMC4
302	102 / RJ6C	605	401 / RS12YC	2384	633 / XML15Y	3095	525 / Z5	AP5263	7437 / RE10PYB5
303	102 / RJ6C	606	13 / RS14YC6	2415	696 / C59R	3116	549 / D18Y	AP5503	3318 / RC12PMC4
304	871 / RJ8C	624	106 / RZF10	2543	403 / RS10LC	3136	842 / UY6	AP605	3401 / RS10PYC4
306	511 / J11C	664	79 / RV15YC6	2544	407 / RS14LC	3176	120 / N5C	AP606	3013 / RS14PYC6
308	592 / RJ12C	665	79 / RV15YC6	2545	407 / RS14LC	3303	400 / RV9YC	AP63	3415 / RN9PYC
312	825 / J4C	666	79 / RV15YC6	2546	407 / RS14LC	3606	79 / RV15YC6	AP64	3322 / RN14PMC3
313	825 / J4C	667	37 / RV17YC6	2553	855 / DJ7Y	3895	412 / RC12LYC	AP646	3031 / RN14PMC5
314	823 / J6C	683	802 / V63C	2554	855 / DJ7Y	3922	430 / RC9YC4	AP65	3405 / RN14PMC
315	841 / J8C	684	108 / RV8C6	2585	101 / RN13LYC	3923	430 / RC9YC4	AP66	3405 / RN14PMC



**CROSS REFERENCE**  
**TABLEAU DE RENVOIS**  
**REFERENCIA CRUZADA**



**CAUTION. DO NOT USE THIS CHART**

UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.

**ATTENTION. NE PAS UTILISER CE TABLEAU**

SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.

**PRECAUCIÓN. NO USE ESTA TABLA**

A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

AUTOLITE	BERU	BOSCH	BOSCH	BOSCH
AP664 3018 / RV17PMC4	162MJ 160 / CH60	4024 406 / RV12YC	4510 9804 / RN8WYPB3	7971 408 / RS14YC
AP665 3018 / RV17PMC4	18GZ577 242 / RB75WPCC	4025 415 / RN9YC	4512 9201 / RC12WYPB4	7972 113 / RV12C
AP666 3018 / RV17PMC4	18GZ677 636 / RB77WPC	4030 3071 / RC12PYC	4515 9901 / RE10WYPB5	7975 406 / RV12YC
AP764 3401 / RS10PYC4	18GZ7 576 / RB76N	4030 7071 / RC12PYP	4516 9006 / REC10WYPB4	7978 401 / RS12YC
AP765 3401 / RS10PYC4	214GK 155 / CH28	4031 304 / RS9YC	6200 21 / RF14YC	7979 401 / RS12YC
AP766 3408 / RS10PYC	348GK 161 / CH61	4033 104 / RN4C	6210 21 / RF14YC	7980 13 / RS14YC6
AP766 7408 / RS14PYPB	368GK 155 / CH28	4035 120 / N5C	6213 7013 / RS14PYP5	7981 20 / RS13LYC5
AP985 3071 / RC12PYC	382GK 161 / CH61	4036 58 / RJ18YC	6224 406 / RV12YC	7982 13 / RS14YC6
APP103 7304 / RS9PYP	601MJ 169 / CH69	4037 3415 / RN9PYP	6231 304 / RS9YC	7983 113 / RV12C
APP104 7963 / RS12PYPB5	602MJ 163 / CH63	4038 332 / RN7YC	6239 7013 / RS14PYP5	7985 18 / RV15YC4
APP105 7940 / RS14PYPB5	603MJ 168 / CH68	4039 7013 / RS14PYP5	6241 3013 / RS14PYP6	7986 18 / RV15YC4
APP106 7408 / RS14PYPB	604MJ 163 / CH63	4041 3013 / RS14PYP6	7302 225 / RB75PP	7989 408 / RS14YC
APP24 7018 / RV17PMP4	613MJ 168 / CH68	4201 3318 / RC12PMC4	7303 217 / RM77PP	7992 332 / RN7YC
APP25 7018 / RV17PMP4	636MJ 168 / CH68	4204 406 / RV12YC	7306 229 / KB77WPCC	7995 415 / RN9YC
APP2544 7407 / RS14ZPYPB	651MJ 168 / CH68	4205 3013 / RS14PYP6	7306 634 / RB77WPCC	7998 104 / RN4C
APP2545 7407 / RS14ZPYPB	663MJ 168 / CH68	4211 7401 / RS12PYP5	7307 242 / RB75WPCC	7999 104 / RN4C
APP26 7018 / RV17PMP4	691MJ 168 / CH68	4214 306 / L86C	7311 642 / RN79G	80003 161 / CH61
APP3923 7546 / RC10PYPB4	724MJ 168 / CH68	4215 104 / RN4C	7313 123 / RN5C	80010 198 / CH260
APP3924 7071 / RC12PYP	<b>BG</b>	4218 404 / RN12YC	7409 809 / RA6HC	80024 180 / CH80
APP5144 7407 / RS14ZPYPB	BG883T 129 / RF10C	4219 404 / RN12YC	7416 809 / RA6HC	80027 184 / CH84
APP5224 7071 / RC12PYP	RB106 598 / RS79N	4220 404 / RN12YC	7510 123 / RN5C	80033 190 / CH237
APP5245 7015 / RS14PMP4	RB1141 565 / RW77N	4221 405 / RN14YC	7533 803 / N4C	80034 191 / CH238
APP5263 7437 / RE10PYPB5	RB126SD 577 / RHW77N	4225 415 / RN9YC	7534 825 / J4C	80036 195 / CH189
APP5364 7032 / RE10PMPB5	RB212 582 / RW82P	4226 409 / RF9YC	7535 823 / J6C	80039 192 / CH271
APP5503 7318 / RC12PMPB4	RB312S 505 / ED89D	4230 7071 / RC12PYP	7539 851 / DJ6J	0241235769 9782 / RC8ZWYPB4
APP605 7963 / RS12PYPB5	RB312S 578 / REW82P	4232 312 / L87YC	7540 847 / DJ8J	241245665 9770 / RC6WYPB3
APP606 7013 / RS14PYP5	RB412 582 / RW82P	4233 104 / RN4C	7542 849 / CJ6	241245670 9770 / RC6WYPB3
APP646 7031 / RN14PMP5	RB442SAW 583 / RHM83N	4235 120 / N5C	7543 843 / CJ8	250001001 155 / CH28
APP65 7332 / RN10PYP4	RB442SW 583 / RHM83N	4236 58 / RJ18YC	7545 853 / CJ7Y	250001008 161 / CH61
APP764 7401 / RS12PYP5	RB485 591 / RM85G	4301 3318 / RC12PMC4	7546 853 / CJ7Y	250001012 161 / CH61
APP765 7401 / RS12PYP5	RB485S 503 / REM84P	4301 7318 / RC12PMPB4	7547 852 / RCJ6Y	250001016 161 / CH61
HT0 7989	RB485S 585 / RHM85G	4302 3018 / RV17PMC4	7700 809 / RA6HC	250200052 160 / CH60
HT1 7989	RB485SA 585 / RHM85G	4303 3318 / RC12PMC4	7701 809 / RA6HC	250200056 163 / CH63
HT15 7989	RB590 620 / RL85G	4304 3408 / RS10PYC	7805 302 / N11YC	250200058 163 / CH63
HT2 7989	RB590S 522 / REL89G	4305 3401 / RS10PYC4	7807 846 / CJ14	250200059 163 / CH63
XP105 9404 / RS14WYPB5	RB792S 551 / RHL79G	4306 3322 / RN14PMC3	7809 841 / J8C	250200060 163 / CH63
XP3923 9001 / RC10WYPB4	RB842S 532 / RHW80N	4307 3322 / RN14PMC3	7810 843 / CJ8	250200063 160 / CH60
XP5263 9901 / RE10WYPB5	RB842SBC 554 / RGC80N	4308 3034 / RC12PEC5	7811 853 / CJ7Y	250200065 163 / CH63
	<b>BERU</b>	4309 3983 / RS14PMPB5	7812 853 / CJ7Y	250200068 163 / CH63
100101302 155 / CH28	RB959S 596 / RHM77N	4310 3415 / RN9PYP	7813 852 / RCJ6Y	250201001 168 / CH68
100101305 161 / CH61	RB959SA 596 / RHM77N	4311 3408 / RS10PYC	7815 847 / DJ8J	250201004 169 / CH69
100101306 155 / CH28	RB993R 530 / RN79G	4312 3071 / RC12PYC	7900 415 / RN9YC	250201005 168 / CH68
100101308 161 / CH61	<b>BMW</b>	4313 3436 / RC12LC4	7905 404 / RN12YC	250201008 168 / CH68
100220101 160 / CH60	12120022902 8809	4314 7346 / RC10PYP4	7907 322 / RN11YC4	250201009 168 / CH68
100220103 160 / CH60	12120030548 353 / RC89TMC	4315 7981 / RE14PYPB4	7908 871 / RJ8C	250201015 169 / CH69
100221102 163 / CH63	12120035933 353 / RC89TMC	4417 7318 / RC12PMPB4	7911 405 / RN14YC	250201019 168 / CH68
100221103 163 / CH63	12129071003 353 / RC89TMC	4418 7318 / RC12PMPB4	7913 405 / RN14YC	250201021 169 / CH69
100221105 169 / CH69	<b>BOSCH</b>	4419 7071 / RC12PYP	7914 322 / RN11YC4	250201027 168 / CH68
100221106 163 / CH63	4000 21 / RF14YC	4428 7034 / RC12PEPB5	7915 592 / RJ12C	250201030 168 / CH68
100221107 168 / CH68	4001 3318 / RC12PMC4	4431 7975 / REC10PYPB4	7916 58 / RJ18YC	250201032 160 / CH60
100221108 163 / CH63	4002 3071 / RC12PYC	4448 7940 / RS14PYPB5	7918 304 / RS9YC	250201032 192 / CH271
100221118 168 / CH68	4003 418 / RC9YCN4	4449 7018 / RV17PMP4	7919 58 / RJ18YC	250202051 148 / CH95
100221133 168 / CH68	4004 3405 / RN14PMC	4458 7401 / RS12PYP5	7922 404 / RN12YC	250202054 149 / CH132
100221138 168 / CH68	4005 406 / RV12YC	4459 7940 / RS14PYPB5	7923 322 / RN11YC4	60999Z 634 / RB77WPCC
100221145 168 / CH68	4006 3013 / RS14PYP6	4469 7983 / RS14PMPB5	7927 71 / RC12YC	60999Z 237 / RB77CC
100221153 168 / CH68	4007 19 / RV19YC	4478 7332 / RN10PYP4	7950 409 / RF9YC	D10A 21 / RF14YC
100221164 168 / CH68	4008 3025 / RV19PMC	4479 7332 / RN10PYP4	7951 22 / RF11YC	D10B 21 / RF14YC
100222201 160 / CH60	4009 3018 / RV17PMC4	4481 7346 / RC10PYP4	7955 71 / RC12YC	D10BC 21 / RF14YC
100271101 184 / CH84	4010 3036 / RV17PZMC	4482 7981 / RE14PYPB4	7956 346 / RC10YC4	D7A 129 / RF10C
100271102 180 / CH80	4011 7401 / RS12PYP5	4488 7437 / RE10PYPB5	7957 71 / RC12YC	D7B 409 / RF9YC
105MJ 163 / CH63	4012 3407 / RS14ZPYP5	4501 9202 / RC12WMPB4	7961 101 / RN13LYC	D8A 129 / RF10C
141M 160 / CH60	4013 3013 / RS14PYP6	4503 9202 / RC12WMPB4	7962 318 / RC12MC4	D8AC 129 / RF10C
141MJ 160 / CH60	4014 306 / L86C	4504 9404 / RS14WYPB5	7963 71 / RC12YC	D8B 409 / RF9YC
143CPU 530 / RN79G	4015 104 / RN4C	4505 9204 / RS12WYPB4	7964 400 / RV9YC	D8BC 409 / RF9YC
14R4ADP 620 / RL85G	4018 3415 / RN9PYP	4506 9804 / RN8WYPB3	7966 304 / RS9YC	D9B 22 / RF11YC
14R4CDP 530 / RN79G	4019 3415 / RN9PYP	4507 9804 / RN8WYPB3	7968 121 / RV8C	D9BC 22 / RF11YC
14R4DP 620 / RL85G	4020 405 / RN14YC	4508 9202 / RC12WMPB4	7969 406 / RV12YC	DR10B 21 / RF14YC
151MJ 163 / CH63	4021 3405 / RN14PMC	4509 9405 / RS14WMPB4	7970 401 / RS12YC	DR10BC 22 / RF11YC



**CAUTION. DO NOT USE THIS CHART**  
 UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.  
**ATTENTION. NE PAS UTILISER CE TABLEAU**  
 SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.  
**PRECAUTION. NO USE ESTA TABLA**  
 A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

BOSCH		BOSCH		BOSCH		BOSCH		BOSCH	
DR10GC0	130 / RF14LC	FR8DPX	418 / RC9YCN4	HR6B	400 / RV9YC	M7AC	506 / D6	W6AC	811 / L82C
DR8B	409 / RF9YC	FR8DS	71 / RC12YC	HR6BC	400 / RV9YC	M8A	509 / D9	W6AS	811 / L82C
DR8BC	409 / RF9YC	FR8HC0X	318 / RC12MC4	HR6DC	304 / RS9YC	M8A0	509 / D9	W6B	312 / L87YC
DR8BPX	409 / RF9YC	FR8HCX	101 / RN13LYC	HR6DP	304 / RS9YC	M8AC0	509 / D9	W6BC	312 / L87YC
DR9B	22 / RF11YC	FR8HP0	3071 / RC12PYC	HR6DS	304 / RS9YC	MR3BPP330	217 / RM77PP	W6BP	811 / L82C
DR9BC	22 / RF11YC	FR8LCX	318 / RC12MC4	HR7DC	304 / RS9YC	MR3DPP33	225 / RB75PP	W6CC	803 / N4C
DR9BPX	21 / RF14YC	FR8LPX	3071 / RC12PYC	HR8A	121 / RV8C	MR3DPP330	1230 / FB77WPCC	W6D	300 / N9YC
F03DAR	430 / RC9YC4	FR8LPX	7071 / RC12PYP	HR8AC	121 / RV8C	U4A	808 / Z9Y	W6D1	300 / N9YC
F04DAR	430 / RC9YC4	FR8LPX	7071 / RC12PYP	HR8ACY	108 / RV8C6	U7A	808 / Z9Y	W6DC	300 / N9YC
F6DC	430 / RC9YC4	FR8T1332	9055 / REC12WMPB5	HR8AY	108 / RV8C6	U7E	842 / UY6	W6DP	300 / N9YC
F6DC0R	430 / RC9YC4	FR8TE2	446 / REC12MCC4	HR8B	406 / RV12YC	UR3AS	889 / Z6	W6DP0	300 / N9YC
F6DP	3344 / RC9PYC	FR9HC	412 / RC12LYC	HR8BC	406 / RV12YC	W06CS	689 / C53R	W7A	306 / L86C
F6DSR	430 / RC9YC4	FR9HP	3405 / RN14PMC	HR8BCY	79 / RV15YC6	W07AS	677 / QL55	W7AC	306 / L86C
F6DTC	430 / RC9YC4	FR9LCX	318 / RC12MC4	HR8BLC0	403 / RS10LC	W07CS	692 / C53	W7B	312 / L87YC
F6DTC1	430 / RC9YC4	FR9LTE	3071 / RC12PYC	HR8BP	406 / RV12YC	W08CS	687 / C59	W7BC	312 / L87YC
F7DC	430 / RC9YC4	H10B	18 / RV15YC4	HR8BPX	406 / RV12YC	W10A	896 / L90C	W7C	803 / N4C
F7LC0R2	3344 / RC9PYC	H5DC	685 / S59YC	HR8DC	401 / RS12YC	W10AC	896 / L90C	W7CC	803 / N4C
F7LDCR	318 / RC12MC4	H6B	400 / RV9YC	HR8DCX	13 / RS14YC6	W10C	504 / N21	W7CC0	803 / N4C
F7LDCR	430 / RC9YC4	H6BC	400 / RV9YC	HR8DCX	408 / RS14YC	W10D	405 / RN14YC	W7CCX	104 / RN4C
F8DC	71 / RC12YC	H6D	304 / RS9YC	HR8DPX	3013 / RS14PYC6	W10DC	405 / RN14YC	W7CX	803 / N4C
F8DC0	71 / RC12YC	H6DC	304 / RS9YC	HR8LPX	15 / RS15LYC	W10E	511 / J11C	W7D	300 / N9YC
F8DPER	3071 / RC12PYC	H6DC0	304 / RS9YC	HR8LPX	7013 / RS14PYP5	W10F	58 / RJ18YC	W7D0	300 / N9YC
F8DPER	7071 / RC12PYP	H7DC	304 / RS9YC	HR9AC	113 / RV12C	W10FC	58 / RJ18YC	W7DC	300 / N9YC
F8DPER	71 / RC12YC	H7DC0	304 / RS9YC	HR9ACY	35 / RV12C6	W12A	896 / L90C	W7DC0	300 / N9YC
F8DPER	9201 / RC12WYPB4	H8B	406 / RV12YC	HR9APX	19 / RV19YC	W12E	846 / CJ14	W7DCX	415 / RN9YC
F8LCR	318 / RC12MC4	H8BC	406 / RV12YC	HR9APX	35 / RV12C6	W2C	805 / N2C	W7DSR	300 / N9YC
F8LCR	412 / RC12LYC	H8DC	401 / RS12YC	HR9B	406 / RV12YC	W2C0	805 / N2C	W7DTC	300 / N9YC
F8LDCR	71 / RC12YC	H8DC0	401 / RS12YC	HR9BC	406 / RV12YC	W2CC	805 / N2C	W7E	823 / J6C
F9DC0	71 / RC12YC	H9B	406 / RV12YC	HR9BCY	79 / RV15YC6	W2CS	687 / C59	W7EC	823 / J6C
FGR7DDP	3318 / RC12PMC4	H9BC	406 / RV12YC	HR9BCZ	37 / RV17YC6	W2D	792 / C59YC	W7F	10 / J12YC
FGR7DQEO	71 / RC12YC	H9BP	18 / RV15YC4	HR9BP	3025 / RV19PMC	W3C	805 / N2C	W7FC	10 / J12YC
FGR7DQI	9202 / RC12WMPB4	H9BPX	18 / RV15YC4	HR9BPX	3018 / RV17PMC4	W3C0	805 / N2C	W8A	306 / L86C
FGR7DQP	7318 / RC12PMPB4	H9DC	401 / RS12YC	HR9BPY	3036 / RV17PZMC	W3CC	805 / N2C	W8A0	306 / L86C
FGR8DDP	3318 / RC12PMC4	H9DC0	401 / RS12YC	HR9BPZ	79 / RV15YC6	W3CS	687 / C59	W8AC	306 / L86C
FGR8DQI	9202 / RC12WMPB4	HGR7KQC	3401 / RS10PYC4	HR9BPZ	3036 / RV17PZMC	W3D	315 / N6YC	W8AP	306 / L86C
FGR8DQP	7318 / RC12PMPB4	HGR7MDPO	3436 / RC12LC4	HR9BPZ	37 / RV17YC6	W3DP	315 / N6YC	W8AS	306 / L86C
FGR8KQC	7071 / RC12PYP	HGR7MQPO	7346 / RC10PYP4	HR9BY	79 / RV15YC6	W3DP0	315 / N6YC	W8B	929 / RL95YC
FGR8LDPO	3034 / RC12PEC5	HGR8BDP	3408 / RS10PYC	HR9D	401 / RS12YC	W3DP2	315 / N6YC	W8BC	929 / RL95YC
FGR8LQIO	9202 / RC12WMPB4	HGR8BQP	7940 / RS14PYPB5	HR9DC	401 / RS12YC	W4A	821 / L77JC4	W8C	120 / N5C
FGR8LQPO	7034 / RC12PEPB5	HGR8DDP	3401 / RS10PYC4	HR9DCX	401 / RS12YC	W4A1	821 / L77JC4	W8C0	120 / N5C
FGR8MQI	9006 / REC10WYPB4	HGR8DQI	9204 / RS12WYPB4	HR9DCY	13 / RS14YC6	W4A2	821 / L77JC4	W8CC	120 / N5C
FGR8MQP	7975 / REC10PYPB4	HGR8DQP	7401 / RS12PYP5	HR9DPX	7401 / RS12PYP5	W4A5	821 / L77JC4	W8D	302 / N11YC
FGR9DDP	3071 / RC12PYC	HGR8MDPO	7346 / RC10PYP4	HR9DPY	3013 / RS14PYC6	W4AC	821 / L77JC4	W8DC	302 / N11YC
FGR9DQI	9201 / RC12WYPB4	HGR8MDPO	7981 / RE14PYPB4	HR9DX	401 / RS12YC	W4AS	821 / L77JC4	W8DC0	404 / RN12YC
FGR9DQP	7071 / RC12PYP	HGR8MQI	9901 / RE10WYPB5	HR9HC	20 / RS13LYC5	W4B2	328 / L82YC	W8DCX	322 / RN11YC4
FLR9LTE	3071 / RC12PYC	HGR8MQPO	7437 / RE10PYPB5	HR9HC0	403 / RS10LC	W4C1	801 / N3C	W8DTC	302 / N11YC
FR10DCX	71 / RC12YC	HGR8MQPO	7981 / RE14PYPB4	HR9HP0	3407 / RS14ZPYC5	W4C2	801 / N3C	W8DX	322 / RN11YC4
FR10DX	71 / RC12YC	HGR9BDP	3018 / RV17PMC4	HR9HPO	3407 / RS14ZPYC5	W4C3	801 / N3C	W8E	841 / J8C
FR3KI332	1221 / RC78WYP15	HGR9BQP	7018 / RV17PMP4	HR9LCX	13 / RS14YC6	W4CC	801 / N3C	W8EC	841 / J8C
FR5DC	430 / RC9YC4	HGR9DDP	3408 / RS10PYC	HR9LCY	15 / RS15LYC	W4CS	801 / N3C	W8F	63 / RJ14YC
FR5DPOR	3344 / RC9PYC	HGR9DQI	9404 / RS14WYPB5	HR9LCY	15 / RS15LYC	W4DP	315 / N6YC	W8FC	63 / RJ14YC
FR5DTC	430 / RC9YC4	HGR9DQP	7940 / RS14PYPB5	HR9LPX	15 / RS15LYC	W4DP0	315 / N6YC	W8LCR	404 / RN12YC
FR6DCX	430 / RC9YC4	HGR9LDPO	3983 / RS14PMC5	HR9LPX	3013 / RS14PYC6	W4E2	825 / J4C	W9A	306 / L86C
FR6DPP332	9770 / RC6WYPB3	HGR9LQIO	9405 / RS14WMPB4	HR9LPX	7013 / RS14PYP5	W5A	807 / L78C	W9A0	844 / H10C
FR6NPP332	9030 / REC8WYPB3	HGR9LQPO	7983 / RS14PMPB5	HS5E	851 / DJ6J	W5AC	807 / L78C	W9AC0	306 / L86C
FR7DC	430 / RC9YC4	HR10A	113 / RV12C	HS8E	847 / DJ8J	W5AS	807 / L78C	W9C	120 / N5C
FR7DC	71 / RC12YC	HR10AC	113 / RV12C	M10A	514 / D14	W5B	328 / L82YC	W9CL	120 / N5C
FR7DCX	346 / RC10YC4	HR10ACY	35 / RV12C6	M10A0	514 / D14	W5BC	328 / L82YC	W9D	405 / RN14YC
FR7DCX	430 / RC9YC4	HR10AY	35 / RV12C6	M10AC0	514 / D14	W5C	803 / N4C	W9DC	405 / RN14YC
FR7DP	3344 / RC9PYC	HR10B	18 / RV15YC4	M12A	516 / D16	W5CC	803 / N4C	W9DC0	405 / RN14YC
FR7DPP	3071 / RC12PYC	HR10BC	18 / RV15YC4	M12B	21 / RF14YC	W5CS	803 / N4C	W9E	511 / J11C
FR7DPX	3318 / RC12PMC4	HR10BCX	18 / RV15YC4	M4A1	506 / D6	W5D	813 / N7YC	W9EC	511 / J11C
FR7DPX	3344 / RC9PYC	HR10BCY	79 / RV15YC6	M4A2	506 / D6	W5D1	813 / N7YC	W9F	58 / RJ18YC
FR7KPP332	9202 / RC12WMPB4	HR10BCZ	79 / RV15YC6	M4AC	506 / D6	W5DC	813 / N7YC	W9FC	58 / RJ18YC
FR8DC	71 / RC12YC	HR10BX	18 / RV15YC4	M5A	506 / D6	W5DP	813 / N7YC	W9H	101 / RN13LYC
FR8DCX	71 / RC12YC	HR10BY	79 / RV15YC6	M5AC	506 / D6	W5DP0	813 / N7YC	WEA	837 / L20V
FR8DCY	89 / RC12YC5	HR10DCX	408 / RS14YC	M5AS	506 / D6	W5E	825 / J4C	WEC	890 / N19V
FR8DPX	3071 / RC12PYC	HR10HC0	407 / RS14LC	M7A	506 / D6	W5EC	825 / J4C	WGR7DDP	3415 / RN9PYC



**CROSS REFERENCE**  
**TABLEAU DE RENVOIS**  
**REFERENCIA CRUZADA**



**CAUTION. DO NOT USE THIS CHART**

UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.

**ATTENTION. NE PAS UTILISER CE TABLEAU**

SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.

**PRECAUCIÓN. NO USE ESTA TABLA**

A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

BOSCH		BOSCH		BRIGGS & STRATTON		DENSO		DENSO	
WGR7DQI	9804 / RN8WYPB3	WR9FP	58 / RJ18YC	492167S	868 / RJ19LM	773831	7712 / QC12PEP	773831	7712 / QC12PEP
WGR8DDP	3322 / RN14PMC3	WR9FPY	66 / RJ18YC6	496018S	431 / RC14YC	K20PRL11	89 / RC12YC5	Q20PRU11	430 / RC9YC4
WGR8DQI	9804 / RN8WYPB3	WR9FPZ	66 / RJ18YC6	72347GS	71 / RC12YC	K20PRU	71 / RC12YC	Q20PRZU11	7346 / RC10PYP4
WGR8DQP	7332 / RN10PYP4	WR9FY	66 / RJ18YC6	72347GS	71G / RC12YC	K20PRU11	89 / RC12YC5	Q20PU	430 / RC9YC4
WGR9DDP	3322 / RN14PMC3	WR9HC	101 / RN13LYC	796112S	868 / RJ19LM	K20RU	3071 / RC12PYC	Q20PU11	430 / RC9YC4
WGR9DQI	9804 / RN8WYPB3	WR9LP	3415 / RN9PYC	802592S	868 / RJ19LM	K20RU	318 / RC12MC4	Q20RU	430 / RC9YC4
WGR9DQP	7332 / RN10PYP4	WR9LS	405 / RN14YC	<b>BRP Spark Plugs</b>		K20RU	3318 / RC12PMC4	Q20RU11	430 / RC9YC4
WR10E	592 / RJ12C	WS12E	846 / CJ14	773831	7712 / QC12PEP	K20RU	7071 / RC12PYP	Q22PRU	430 / RC9YC4
WR10F	58 / RJ18YC	WS5E	862 / CJ4	5001111	7712 / QC12PEP	K20RU	71 / RC12YC	Q22PRZU	7346 / RC10PYP4
WR10FC	58 / RJ18YC	WS5F	858 / CJ6Y	5001211	955	K20RU	7318 / RC12PMPB4	Q24PRZU11	340 / RC7YC
WR10FCY	66 / RJ18YC6	WS7E	849 / CJ6	278002297	1009 / NI039Y	K20RU	9201 / RC12WYWPB4	QJ16HRU	412 / RC12LYC
WR10FCZ	66 / RJ18YC6	WS7F	853 / CJ7Y	402297942	905 / RA4HC	K20RU	9202 / RC12WMPB4	QJ20CR11	318 / RC12MC4
WR10FY	66 / RJ18YC6	WS8E	843 / CJ8	707000246	809 / RA6HC	K20RU11	89 / RC12YC5	SC20HR11	9412 / REA9WYWPB4
WR10LC	404 / RN12YC	WS8F	853 / CJ7Y	<b>CASE</b>		K22PRU	430 / RC9YC4	SF10	824 / UL18V
WR10LCV	31 / RN14MC5	WS9E	846 / CJ14	AO5999AB	841 / J8C	KJ14CRL11	318 / RC12MC4	SF50	827
WR10LCV	322 / RN11YC4	WSR6F	852 / RCJ6Y	AO5999B	841 / J8C	KJ16CR11	318 / RC12MC4	SF51	833
WR11EC0	592 / RJ12C	X2C	662 / A59C	TG44840	516 / D16	KJ16CRL11	318 / RC12MC4	SK16HR11	9006 / REC10WYWPB4
WR3CPP33	642 / RN79G	X4A	816 / P7	TM20007	844 / H10C	KJ20CR11	318 / RC12MC4	SK16PRA11	9201 / RC12WYWPB4
WR3CTC	818 / RN2C	X4C	809 / RA6HC	TM20699	306 / L86C	KJ20CRL11	318 / RC12MC4	SK16PRE13	9008 / RC10WYWPB5
WR4DP0	339 / RN6YC	X5DC	809 / RA6HC	<b>CATERPILLAR</b>		L14RU	541 / RD16	SK16R11	9001 / RC10WYWPB4
WR5DC	332 / RN7YC	X7A	816 / P7	23643	516 / D16	L14U	516 / D16	SK20HR11	9033 / REC8WYWPB4
WR5DP	332 / RN7YC	XR2AS	816 / P7	1948518	229 / KB77WPCC	M14	516 / D16	SK20PRA8	9802 / RC8WYWPB4
WR5DS	332 / RN7YC	XR2CS	809 / RA6HC	2848313	KB77WPCC	M17	514 / D14	SK20R11	318 / RC12MC4
WR6DC	415 / RN9YC	XR2CS	905 / RA4HC	2A3643	516 / D16	M22	509 / D9	SK20R11	3318 / RC12PMC4
WR6DP	415 / RN9YC	XR4CS	809 / RA6HC	2B9548	569 / W14	M24S	506 / D6	SK20R11	7318 / RC12PMPB4
WR6DS	415 / RN9YC	XR5DC	809 / RA6HC	2W9486	300 / N9YC	MA14PU	21 / RF14YC	SK20R11	9806 / RC8WMPB4
WR7BP	312 / L87Y	Y6DC	809 / RA6HC	3B6583	844 / H10C	MA16PRU	22 / RF11YC	SK22PRM1S	9800 / RC6WYWPB4
WR7CC	104 / RN4C	YR7LPP332W	9702 / KA7ZWYWPB4	8F6347	843 / CJ8	MA16PRU11	22 / RF11YC	SK22PRM1S	9800 / RC6WYWPB4
WR7CCX	104 / RN4C	<b>BRIGGS &amp; STRATTON</b>		9B0444	823 / J6C	MA16PRU15	22 / RF11YC	SKJ20DRM11	9812 / RC8ZWYWPB4
WR7CE	123 / RN5C	5062	973 / RJ19HX	9M4141	10 / J12YC	MA16PU	22 / RF11YC	SKJ20DRM11S	9812 / RC8ZWYWPB4
WR7CP	104 / RN4C	5066	3071 / RC12PYC	9M4142	10 / J12YC	MA16RU	129 / RF10C	SXU22HCR11S	9407 / RER8ZWYCB4
WR7CPX	104 / RN4C	5092	431 / RC14YC	<b>CHRYSLER</b>		MA17PU	22 / RF11YC	T16EPRU	408 / RS14YC
WR7DC	415 / RN9YC	5095	868 / RJ19LM	04606591AB	7034 / RC12PEPB5	MA20PRU	409 / RF9YC	T16EPRU15	13 / RS14YC6
WR7DS	415 / RN9YC	491055	71 / RC12YC	5149002AA	443 / RE16MC	MA20PU	409 / RF9YC	T16NRU11	407 / RS14LC
WR7DSR	415 / RN9YC	491055	71G / RC12YC	68005667AA	9408 / RER8WYCB4	MA20RU	129 / RF10C	T16PRU	18 / RV15YC4
WR7DTC	415 / RN9YC	499608	71 / RC12YC	SP0RC12LC4	7436 / RC10PLPB4	MA20RU11	129 / RF10C	T16PRU11	18 / RV15YC4
WR7F	14 / RJ12YC	499608	71G / RC12YC	SP0RE10PM5	3132 / RE10PMC5	MA9PRU	21 / RF14YC	T16PRU15	79 / RV15YC6
WR8CP	120 / N5C	499730	973 / RJ19HX	SPLZTR5A13	7570 / RE14PMPB	MA9PU	21 / RF14YC	T16PRU20	79 / RV15YC6
WR8D	404 / RN12YC	691043	946 / QC12YC	<b>CUB CADET</b>		MW17U	514 / D14	T16PU	18 / RV15YC4
WR8DC	404 / RN12YC	692051	71 / RC12YC	759336	71 / RC12YC	MW22U	509 / D9	T16RU	113 / RV12C
WR8DCX	322 / RN11YC4	692051	71G / RC12YC	75110292	415 / RN9YC	P16PR11	3322 / RN14PMC3	T16RU15	35 / RV12C6
WR8DP	3415 / RN9PYC	692720	946 / QC12YC	9807956846	415 / RN9YC	P16R	3322 / RN14PMC3	T20EPRU	401 / RS12YC
WR8DP	404 / RN12YC	694385	5071	<b>DENSO</b>		P20PR11	7346 / RC10PYP4	T20EPRU15	13 / RS14YC6
WR8DPX	3415 / RN9PYC	694385	711 / RC12YC	FK16HQR11	9006 / REC10WYWPB4	P20PR13	7346 / RC10PYP4	T20PU	401 / RS12YC
WR8DPX	404 / RN12YC	694385	71EZ / 71EZ	FK20HR11	9006 / REC10WYWPB4	P20PRS11	7346 / RC10PYP4	T20EXU	401 / RS12YC
WR8DS	322 / RN11YC4	694385	71G / RC12YC	FXE22HR11	9412 / REA9WYWPB4	PK16R	7071 / RC12PYP	T20MPU	855 / DJ7Y
WR8E	871 / RJ8C	696073	5071	F XU16HR11	9047 / RER12WMPB4	PK16R11	7071 / RC12PYP	T20MU	847 / DJ8J
WR8EC	871 / RJ8C	696073	711 / RC12YC	GE31	642 / RN79G	PK20PR11	7071 / RC12PYP	T20NRU11	403 / RS10LC
WR8F	63 / RJ14YC	696073	71EZ / 71EZ	GI31A	1230 / FB77WPCC	PK20PRL11	7071 / RC12PYP	T20PRU	406 / RV12YC
WR8FC	63 / RJ14YC	696073	71G / RC12YC	GI33A	1230 / FB77WPCC	PK20PRP11	7071 / RC12PYP	T20PRU11	406 / RV12YC
WR9A0	854 / RH10C	696202	3071 / RC12PYC	GL31A	242 / RB75WPCC	PK20R11	7071 / RC12PYP	T20PRU15	79 / RV15YC6
WR9C	123 / RN5C	696798	5071	GL33A	242 / RB75WPCC	PK20R8	7071 / RC12PYP	T20PU	406 / RV12YC
WR9CC	123 / RN5C	696798	711 / RC12YC	IKH20	9006 / REC10WYWPB4	PK20TR11	7071 / RC12PYP	T20RU	121 / RV8C
WR9D	405 / RN14YC	696798	71EZ / 71EZ	IXU27	1006 / RA59GC	PKJ20CRL11	7071 / RC12PYP	T20RU15	108 / RV8C6
WR9DC	405 / RN14YC	696798	71G / RC12YC	IXU27	7622 / RA59PP	PQ16R	7071 / RC12PYP	T22EPU	344 / RC9YC
WR9DCX	405 / RN14YC	711252	71G / RC12YC	J16ARU11	322 / RN11YC4	PQ16R8	7071 / RC12PYP	T22MPU	855 / DJ7Y
WR9DCY	105 / RN16YC5	792015	71 / RC12YC	J16BRU	101 / RN13LYC	PQ20PRP8	7071 / RC12PYP	T22MU	851 / DJ6J
WR9DCY	322 / RN11YC4	792015	71G / RC12YC	J16BRU11	101 / RN13LYC	PQ20R	7071 / RC12PYP	TR14PRU	25 / RV17YC
WR9DP	405 / RN14YC	796560	5861	J16HRU10	101 / RN13LYC	PQ20R11	7071 / RC12PYP	TR14PRU15	37 / RV17YC6
WR9DPX	3405 / RN14PMC	799876	5861	K16GPRU11	318 / RC12MC4	PQ20RP8	7071 / RC12PYP	U14U	842 / UY6
WR9DPX	405 / RN14YC	799876	861EZ / 861EZ	K16PRL11	318 / RC12MC4	Q16HRU	412 / RC12LYC	U16FSU	808 / Z9Y
WR9DS	405 / RN14YC	799876	868 / RJ19LM	K16PRT11	318 / RC12MC4	Q16PRU	71 / RC12YC	U17FU	808 / Z9Y
WR9E	592 / RJ12C	799876	8681 / RJ19LM	K16PRU	71 / RC12YC	Q16PRU11	71 / RC12YC	U17U	842 / UY6
WR9EC	592 / RJ12C	799876	868LMC	K16PRU11	318 / RC12MC4	Q16PRU15	89 / RC12YC5	U20FBU	808 / Z9Y
WR9F	58 / RJ18YC	805015	71 / RC12YC	K16R4	89 / RC12YC5	Q16PRZU11	7071 / RC12PYP	U20FSRU	808 / Z9Y
WR9FC	58 / RJ18YC	805015	71G / RC12YC	K16RU	71 / RC12YC	Q16PRZU15	7071 / RC12PYP	U20FSU	808 / Z9Y
WR9FCY	66 / RJ18YC6	491055S	71 / RC12YC	K16RU11	89 / RC12YC5	Q16RU	71 / RC12YC	U20FSZU	808 / Z9Y
WR9FCZ	66 / RJ18YC6	491055S	71G / RC12YC	K20HRU11	9033 / REC8WYWPB4	Q16RU11	71 / RC12YC	U20FU	808 / Z9Y



**CAUTION. DO NOT USE THIS CHART**  
 UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.  
**ATTENTION. NE PAS UTILISER CE TABLEAU**  
 SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.  
**PRECAUTION. NO USE ESTA TABLA**  
 A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

DENSO		DENSO		DENSO		DENSO		E3 SPARK PLUGS	
U20MU	877 / Y82	W16PU	63 / RJ14YC	W22FU	306 / L86C	X20FU	888 / P8Y	E310	5861
U22FBU	808 / Z9Y	W16SU	841 / J8C	W22MPU	853 / CJ7Y	X20FWU	888 / P8Y	FF16	851EZ / 851EZ
U22FSRU	808 / Z9Y	W17ESU	120 / N5C	W22MU	849 / CJ6	X22EPRGL	810 / RA8HC	FF18	104 / RN4C
U22FSU	808 / Z9Y	W17EWU	300 / N9YC	W22MUS	849 / CJ6	X22EPRZU9	810 / RA8HC	FF18	803 / N4C
U22FSZU	808 / Z9Y	W17FU	306 / L86C	W22SU	823 / J6C	X22EPU9	810 / RA8HC	FF20	5071
U22FU	808 / Z9Y	W17PU	10 / J12YC	W22U	823 / J6C	X22EPZU9	810 / RA8HC	FF20	71 / RC12YC
U24FBU	889 / Z6	W17U	823 / J6C	W24EPRU	332 / RN7YC	X22ESRU	810 / RA8HC	FF20	71EZ / 71EZ
U24FSRU	889 / Z6	W20EKPRS11	415 / RN9YC	W24EPU	813 / N7YC	X22ESU	810 / RA8HC	FF22	300 / N9YC
U24FSU	889 / Z6	W20EKRS11	415 / RN9YC	W24ESRU	880 / RN3C	X22ESZU	810 / RA8HC	FF22	415 / RN9YC
U24FU	889 / Z6	W20EPRU	322 / RN11YC4	W24ESRV	688 / C61	X22EU	810 / RA8HC		
U27FSZU	889 / Z6	W20EPRU10	322 / RN11YC4	W24ESU	801 / N3C	X22FU	816 / P7		
U31ESZU	653 / G57C	W20EPRU11	322 / RN11YC4	W24ESU11	801 / N3C	X24EPRU9	809 / RA6HC		
U31FSZU	889 / Z6	W20EPU	300 / N9YC	W24ESV	688 / C61	X24EPRZU9	809 / RA6HC		
VX22BC	8812	W20EPU11	322 / RN11YC4	W24ESZU	801 / N3C	X24EPU9	809 / RA6HC		
W14E	120 / N5C	W20EPZU	300 / N9YC	W24EU	801 / N3C	X24EPZU9	809 / RA6HC		
W14EKRS11	405 / RN14YC	W20ESL	803 / N4C	W24FPU	328 / L82YC	X24ESRU	809 / RA6HC		
W14EPRU	405 / RN14YC	W20ESL11	803 / N4C	W24FSR	830 / RL86C	X24ESU	809 / RA6HC		
W14EPU	405 / RN14YC	W20ESRL	104 / RN4C	W24FSU	811 / L82C	X24ESZU	809 / RA6HC		
W14EXRU	405 / RN14YC	W20ESRL11	104 / RN4C	W24FSZU	811 / L82C	X24EU	809 / RA6HC		
W14EXRU11	405 / RN14YC	W20ESRU	104 / RN4C	W24FU	811 / L82C	X24FSRU	816 / P7		
W14EXRU15	31 / RN14MC5	W20ESU	803 / N4C	W24SU	825 / J4C	X24FSU	816 / P7		
W14EXU	405 / RN14YC	W20ESU11	308 / RN12MC4	W24U	825 / J4C	X24FSZU	816 / P7		
W14EXU11	405 / RN14YC	W20ESZU	803 / N4C	W25ECU	807 / L78C	X27EPRU9	905 / RA4HC		
W14FPR	929 / RL95YC	W20ETRS	415 / RN9YC	W27ENU	696 / C59R	X27EPRZU9	905 / RA4HC		
W14FPRUL	929 / RL95YC	W20ETS	300 / N9YC	W27ESRU	818 / RN2C	X27EPZU9	905 / RA4HC		
W14FPU	929 / RL95YC	W20EXRU	415 / RN9YC	W27ESRV	688 / C61	X27ESRU	661 / A57C		
W14FPUL	929 / RL95YC	W20EXRU11	415 / RN9YC	W27ESU	805 / N2C	X27ESU	661 / A57C		
W14FPUL10	929 / RL95YC	W20EXU	300 / N9YC	W27ESV	688 / C61	X27ESZU	661 / A57C		
W14FRU	830 / RL86C	W20EXU11	300 / N9YC	W27ESZU	687 / C59	X28FSU	816 / P7		
W14FRU	896 / L90C	W20EXU13	300 / N9YC	W27FSR	883 / QL78C	X29ESZU	661 / A57C		
W14FU	896 / L90C	W20FPRL	929 / RL95YC	W27FSU	807 / L78C	XZU20HCR8	9060 / RER11WMPB3		
W14L	844 / H10C	W20FPRU	929 / RL95YC	W27FSU10	807 / L78C				
W14LMU	861 / J19LM	W20FPU	312 / L87YC	W27FSZU	807 / L78C				
W14LMUS	861 / J19LM	W20FPU	929 / RL95YC	W27SU	825 / J4C				
W14MPRU10	863 / RCJ8Y	W20FSR	830 / RL86C	W29ENU	690 / C57R				
W14MPU10	848 / CJ8Y	W20FSU	306 / L86C	W29ESRV	687 / C59				
W14MRU	868 / RJ19LM	W20FSZU	306 / L86C	W29ESV	687 / C59				
W14MU	846 / CJ14	W20MPRU10	863 / RCJ8Y	W29ESZU	687 / C59				
W14MU10	846 / CJ14	W20MPU	848 / CJ8Y	W31ENU	695 / C55R				
W14MUS	846 / CJ14	W20MPU10	848 / CJ8Y	W31ESU	686 / C57				
W14PRU	58 / RJ18YC	W20MRU	840 / RCJ8	W31ESZU	687 / C59				
W14PRU15	66 / RJ18YC6	W20MU	843 / CJ8	W31FS	821 / L77JC4				
W14PU	58 / RJ18YC	W20MUS	843 / CJ8	W31FSZU	677 / QL55				
W14U	841 / J8C	W20PRU	14 / RJ12YC	W31SU	825 / J4C				
W14US	841 / J8C	W20PU	10 / J12YC	W34ENU	689 / C53R				
W16EKRS11	322 / RN11YC4	W20SRU	102 / RJ6C	W37ENU	689 / C53R				
W16EPRS11	322 / RN11YC4	W20SU	823 / J6C	W9EP	405 / RN14YC				
W16EPRU	322 / RN11YC4	W21ESL11	801 / N3C	W9EU	504 / N21				
W16EPRU10	322 / RN11YC4	W21ESRL11	880 / RN3C	W9FP	929 / RL95YC				
W16EPU	302 / N11YC	W22EPRS11	322 / RN11YC4	W9PRU	58 / RJ18YC				
W16EPU10	322 / RN11YC4	W22EPRU	415 / RN9YC	W9PRU15	66 / RJ18YC6				
W16EPZU	302 / N11YC	W22EPRU11	415 / RN9YC	W9PRU20	66 / RJ18YC6				
W16ESL	120 / N5C	W22EPU	300 / N9YC	W9PU	58 / RJ18YC				
W16ESL11	120 / N5C	W22EPZU	300 / N9YC	W9U	592 / RJ12C				
W16ESRU	123 / RN5C	W22ESL	805 / N2C	WA20MU	847 / DJ8J				
W16ESU	120 / N5C	W22ESL11	805 / N2C	WA22MU	851 / DJ6J				
W16EXRU	322 / RN11YC4	W22ESRL11	415 / RN9YC	WS20SU	102 / RJ6C				
W16EXRU11	322 / RN11YC4	W22ESRU	880 / RN3C	WU14EU	120 / N5C				
W16EXU	302 / N11YC	W22ESU	801 / N3C	WU9EU	120 / N5C				
W16EXU11	322 / RN11YC4	W22ESU11	801 / N3C	X16FSRU	910 / P10Y				
W16EXU13	322 / RN11YC4	W22ESZU	801 / N3C	X16FSU	910 / P10Y				
W16FPR	929 / RL95YC	W22EU	120 / N5C	X17FU	816 / P7				
W16FPU	929 / RL95YC	W22EXU	813 / N7YC	X20EPRU9	810 / RA8HC				
W16FSR	830 / RL86C	W22FPRU	327 / RL87YC	X20ESU	810 / RA8HC				
W16FSU	306 / L86C	W22FPU	312 / L87YC	X20EU	810 / RA8HC				
W16LS	587 / H8C	W22FSR	830 / RL86C	X20FSRU	888 / P8Y				
W16PRU	63 / RJ14YC	W22FSU	306 / L86C	X20FSU	888 / P8Y				
W16PRU15	66 / RJ18YC6	W22FSZU	306 / L86C	X20FSZU	888 / P8Y				



**CROSS REFERENCE**  
**TABLEAU DE RENVOIS**  
**REFERENCIA CRUZADA**



**CAUTION. DO NOT USE THIS CHART**

UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.

**ATTENTION. NE PAS UTILISER CE TABLEAU**

SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.

**PRECAUCIÓN. NO USE ESTA TABLA**

A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

HONDA		MAZDA		MOPAR		MOPAR		MOTORCRAFT	
9807B5615W	9812 / RC8ZWYPB4	000018L3Y2	9901 / RE10WYPB5	2444870	63 / RJ14YC	SP00ZFR5AP	3720 / RC12PMCB3	AES4C	830 / RL86C
9807B5617W	9014 / RC8ZWYPB	1F7218110	403 / RS10LC	2642475	63 / RJ14YC	SP0ZFR5F11	9202 / RC12WMPB4	AF1	802 / V63C
9807B561CW	9812 / RC8ZWYPB4	L30318110	9008 / RC10WYPB5	2642913	10 / J12YC	SP149125AD	9407 / RER8ZWYCB4	AF12	400 / RV9YC
9807B56A5W	9813 / RC8ZWYPB5	L3Y218110	9901 / RE10WYPB5	3438334	63 / RJ14YC	SPLZFR5C11	446 / REC12MCC4	AF2	802 / V63C
9807B56A7W	9202 / RC12WMPB4	L3YD18110	9016 / RES8WYCB5	3874934	18 / RV15YC4	SPZFR6F11G	9002 / RC10WMPB4	AF22	400 / RV9YC
9807B56A7W	9813 / RC8ZWYPB5	LFJD18110	9901 / RE10WYPB5	4091678	25 / RV17YC	SVRE10PMCS	3032 / RE10PMCS	AF2C	802 / V63C
N1039Y	1009S / N1039Y	PE0118110	9901 / RE10WYPB5	4091713	404 / RN12YC	SZFR5LP13G	7034 / RC12PEPB5	AF3	121 / RV8C
RDJ8J	847EZ / 847EZ	PE0218110	9901 / RE10WYPB5	4091933	14 / RJ12YC	<b>MOTORCRAFT</b>			
RDZ4H	979 / RDZ4H	PE5R18110	9901 / RE10WYPB5	4091936	63 / RJ14YC	4C3Z12A342AA	194 / CH243	AF32	406 / RV12YC
XC10YC	988 / XC10YC	ZJY618110	9008 / RC10WYPB5	4091938	400 / RV9YC	A11	592 / RJ12C	AF3C	121 / RV8C
<b>HYUNDAI</b>		<b>MERCEDES-BENZ</b>		4106117	415 / RN9YC	A11LM	861 / J19LM	AF3NX	851 / DJ6J
188171105	7546 / RC10PYPB4	0041591803	7019 / KER8PYPB	4106122	300 / N9YC	A11NX	846 / CJ14	AF42	406 / RV12YC
188251101	9007 / RN10WYPB5	<b>MIGHTY</b>		4141705	406 / RV12YC	A11X	592 / RJ12C	AF42C	406 / RV12YC
188261101	7346 / RC10PYP4	M43	823 / J6C	4289155	25 / RV17YC	A21X	825 / J4C	AF52	18 / RV15YC4
188451160	9006 / REC10WYPB4	M432	10 / J12YC	4289165	129 / RF10C	A22	10 / J12YC	AF52C	18 / RV15YC4
1884611070	9023 / RER10WMPB4	M442	10 / J12YC	4318130	302 / N11YC	A22NX	853 / CJ7Y	AF5NX	850 / DJ7J
1884708200	9060 / RER11WMPB3	M452	63 / RJ14YC	4318131	322 / RN11YC4	A2C	102 / RJ6C	AF701	670 / V59C
1884708220	9060 / RER11WMPB3	M4E4	306 / L86C	4318134	401 / RS12YC	A2C	825 / J4C	AF901	802 / V63C
1884711160	9047 / RER12WMPB4	M4F42	406 / RV12YC	4318135	406 / RV12YC	A2NX	825 / J4C	AG040	415 / RN9YC
2741023700	7546 / RC10PYPB4	M4G22	300 / N9YC	4318138	82 / RFN14LY	A32	10 / J12YC	AG091	332 / RN7YC
2741023700	9003 / RC10WYPB4	M4G3	120 / N5C	4339413	18 / RV15YC4	A3NX	849 / CJ6	AG092C	315 / N6YC
2741037100	7546 / RC10PYPB4	M4G32	302 / N11YC	4339415	25 / RV17YC	A3X	823 / J6C	AG092C	339 / RN6YC
274103C000	9003 / RC10WYPB4	M4G32A	302 / N11YC	4339416	37 / RV17YC6	A42	10 / J12YC	AG12	813 / N7YC
<b>ISUZU</b>		M4G4	120 / N5C	4339420	113 / RV12C	A42C	10 / J12YC	AG14	101 / RN13LYC
8125980040	9901 / RE10WYPB5	M4G42	38 / N12YC	4339425	14 / RJ12YC	A5	841 / J8C	AG1CX	801 / N3C
<b>JAGUAR</b>		M4G52	38 / N12YC	4339427	22 / RF11YC	A52	63 / RJ14YC	AG1X	801 / N3C
AJ812146	9412 / REA9WYPB4	M4GR22	415 / RN9YC	4339428	66 / RJ18YC6	A5X	841 / J8C	AG2	803 / N4C
C2P23089	9412 / REA9WYPB4	M4GR32	322 / RN11YC4	4339429	400 / RV9YC	A6S	557 / XEJ8	AG22	300 / N9YC
<b>JOHN DEERE</b>		M4GR42	404 / RN12YC	4339430	409 / RF9YC	A7	841 / J8C	AG22C	300 / N9YC
M78543	71 / RC12YC	M4GR52	404 / RN12YC	4339487	813 / N7YC	A7C	841 / J8C	AG2X	803 / N4C
M805853	405 / RN14YC	M4GR526	105 / RN16YC5	4339491	841 / J8C	A7CLM	845 / J17LM	AG3	120 / N5C
<b>KIA</b>		M4GRF32	401 / RS12YC	4339492	121 / RV8C	A7CX	841 / J8C	AG32	302 / N11YC
1885409080	445 / RER8MC	M4GRF52	408 / RS14YC	4419643	843 / CJ8	A7LM	845 / J17LM	AG32A	302 / N11YC
<b>KOHLER</b>		M4R32	14 / RJ12YC	4504278	304 / RS9YC	A7N	843 / CJ8	AG32C	38 / N12YC
1413203	71 / RC12YC	M4R42	14 / RJ12YC	4504279	430 / RC9YC4	A7NX	843 / CJ8	AG3C	120 / N5C
1213202S	71 / RC12YC	M4R426	66 / RJ18YC6	4504290	844 / H10C	A7X	841 / J8C	AG3X	120 / N5C
2513212S	3071 / RC12PYC	M4R52	63 / RJ14YC	4609079	89 / RC12YC5	A82	58 / RJ18YC	AG4	120 / N5C
2513214S	982 / XC12YC	M4R826	66 / RJ18YC6	4609081	308 / RN12MC4	A8S	567 / XEJ12	AG403	690 / C57R
5213202S	25 / RV17YC	M4R828	66 / RJ18YC6	4671057	344 / RC9YC	A9	511 / J11C	AG42	38 / N12YC
<b>LANDROVER</b>		M4RF22	400 / RV9YC	4686083	31 / RN14MC5	A901	825 / J4C	AG42C	38 / N12YC
ERR3799	322 / RN11YC4	M4RF32	406 / RV12YC	4727114	7031 / RN14PMP5	A9X	511 / J11C	AG44	101 / RN13LYC
ERR743	415 / RN9YC	M4RF4	121 / RV8C	4796779	7346 / RC10PYP4	AE091	807 / L78C	AG5	120 / N5C
ETC7244	404 / RN12YC	M4RF42	406 / RV12YC	4864454	2071	AE091X	821 / L77JC4	AG501	686 / C57
NLP100290L	7545 / RC8PYPB4	M4RF426	79 / RV15YC6	4864457	2319	AE1X	807 / L78C	AG501X	686 / C57
NLP100320	7070 / RC11PYPB4	M4RF46	108 / RV8C6	4864459	2412	AE2	811 / L82C	AG52	38 / N12YC
RTC3812	300 / N9YC	M4RF52	18 / RV15YC4	4864461	2095	AE22	328 / L82YC	AG52C	38 / N12YC
<b>LUCAS</b>		M4RF526	79 / RV15YC6	5213693	404 / RN12YC	AE22C	328 / L82YC	AG54	101 / RN13LYC
DS002	169 / CH69	M4RF62	25 / RV17YC	5234975	109	AE2X	811 / L82C	AG603	696 / C59R
DS003	168 / CH68	M4RF626	37 / RV17YC6	5369556	426 / RC9YC5	AE3	811 / L82C	AG7	120 / N5C
DS004	160 / CH60	M4RF8	113 / RV12C	56006240	71 / RC12YC	AE32	312 / L87YC	AG701	688 / C61
DS006	163 / CH63	M4RF86	35 / RV12C6	56027108	434 / RC9MC4	AE3X	811 / L82C	AG82	405 / RN14YC
DS090	180 / CH80	M4WRF42	401 / RS12YC	56027275	412 / RC12LYC	AE3XF	811 / L82C	AG9	504 / N21
DS092	184 / CH84	M8F32	409 / RF9YC	82300312	880 / RN3C	AE4	306 / L86C	AG901	805 / N2C
DS101	161 / CH61	M8F42	22 / RF11YC	82300313	430 / RC9YC4	AE42	929 / RL95YC	AG901X	805 / N2C
DS104	155 / CH28	M8F82	22 / RF11YC	82300314	89 / RC12YC5	AE42C	929 / RL95YC	AGF12	304 / RS9YC
<b>MASSEY-FERGUSON</b>		M8RF31	129 / RF10C	82300315	308 / RN12MC4	AE4C	306 / L86C	AGKO	890 / N19V
1060024MI	406 / RV12YC	M8RF42	22 / RF11YC	82300316	101 / RN13LYC	AE4X	306 / L86C	AGR14	101 / RN13LYC
834225MI	841 / J8C	M8RF82	22 / RF11YC	82300317	405 / RN14YC	AE6	896 / L90C	AGR1X	880 / RN3C
834230MI	841 / J8C	M8TF31	129 / RF10C	82300318	407 / RS14LC	AE62	929 / RL95YC	AGR21	104 / RN4C
834232MI	511 / J11C	<b>MITSUBISHI</b>		82300319	408 / RS14YC	AE7	896 / L90C	AGR22	415 / RN9YC
834234MI	306 / L86C	1822A002	9801 / RC8WYPB3	82300320	13 / RS14YC6	AER2X	874 / RL82C	AGR22C	415 / RN9YC
834236MI	38 / N12YC	1822A068	9002 / RC10WMPB4	82300321	15 / RS15LYC	AER32	327 / RL87YC	AGR2X	104 / RN4C
834237MI	22 / RF11YC	1822A069	9806 / RC8WMPB4	82300322	79 / RV15YC6	AER3S	612 / RML12	AGR31	123 / RN5C
834241MI	22 / RF11YC	MN158596	7975 / REC10PYPB4	82300323	11 / RF18YC	AER3SA	603 / XML12	AGR32	322 / RN11YC4
834241MI	516 / D16	MN163807	9801 / RC8WYPB3	82300324	17 / RV19YC6	AER4	830 / RL86C	AGR32C	404 / RN12YC
834245MI	120 / N5C	MR984943	9802 / RC8WYPB4	82300325	909 / RS17YX	AER4S	610 / REL88B	AGR3S	616 / XMN12
834247MI	306 / L86C	<b>MOPAR</b>		82300326	129 / RF10C	AER4X	830 / RL86C	AGR3X	123 / RN5C
834248MI	129 / RF10C	2098360	38 / N12YC	S3RE14PLP5	7440 / RE14PLP5	AER72S	633 / XML15Y	AGR41	123 / RN5C





**CAUTION. DO NOT USE THIS CHART**  
 UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.  
**ATTENTION. NE PAS UTILISER CE TABLEAU**  
 SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.  
**PRECAUTION. NO USE ESTA TABLA**  
 A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

MOTORCRAFT		MOTORCRAFT		MOTORCRAFT		MOTORCRAFT		MOTORCRAFT	
AGR42	404 / RN12YC	AGSP54	412 / RC12LYC	AS8	861 / J19LM	AWSF42	401 / RS12YC	BT8	516 / D16
AGR42C	404 / RN12YC	AGSP54C	412 / RC12LYC	AS827	66 / RJ18YC6	AWSF42C	401 / RS12YC	BT9	502 / D21
AGR44	101 / RN13LYC	AL11	512 / H12	AS82C7	66 / RJ18YC6	AWSF42EE	7401 / RS12PYP5	BTF1	129 / RF10C
AGR4S	614 / XEN14	AL5	844 / H10C	AS8S	567 / XEJ12	AWSF42P	3401 / RS10PYC4	BTF3	129 / RF10C
AGR51	123 / RN5C	AL52	91 / H14Y	ASF22C	400 / RV9YC	AWSF42PP	7401 / RS12PYP5	BTF31	129 / RF10C
AGR52	404 / RN12YC	AL5X	587 / H8C	ASF32	406 / RV12YC	AWSF44	407 / RS14LC	BTF314	129 / RF10C
AGR526	105 / RN16YC5	AL7	844 / H10C	ASF32C	406 / RV12YC	AWSF44C	407 / RS14LC	BTF42	22 / RF11YC
AGR54	101 / RN13LYC	AL7C	844 / H10C	ASF32C6	79 / RV15YC6	AWSF44EE	7407 / RS14ZPYPB	BTF6	129 / RF10C
AGR82	405 / RN14YC	AL7X	844 / H10C	ASF32CM	406 / RV12YC	AWSF44P	3407 / RS14ZPYC5	BTRF42	22 / RF11YC
AGR8S	614 / XEN14	AL82	857 / RH18Y	ASF32M	406 / RV12YC	AWSF44PP	7407 / RS14ZPYPB	BTS8	516 / D16
AGRF2	304 / RS9YC	AL9	844 / H10C	ASF32P	3018 / RV17PMC4	AWSF52	401 / RS12YC	BYRF314	106 / RZF10
AGRF22	304 / RS9YC	AL9X	844 / H10C	ASF34	406 / RV12YC	AWSF52C	401 / RS12YC	BYSF314	106 / RZF10
AGRF32	401 / RS12YC	AR10	592 / RJ12C	ASF3C	121 / RV8C	AWSF54	407 / RS14LC	BYSF34	106 / RZF10
AGRF42	401 / RS12YC	AR10S	567 / XEJ12	ASF3C6	108 / RV8C6	AWSF54C	407 / RS14LC	BZ8	555 / UD16
AGRF52	408 / RS14YC	AR21X	825 / J4C	ASF42	406 / RV12YC	AWSF32C	401 / RS12YC	CGSF22F	9204 / RS12WYPB4
AGS081C	805 / N2C	AR31	871 / RJ8C	ASF42C	406 / RV12YC	AYFS092FEC	7437 / RE10PYPB5	CGSF22N	9204 / RS12WYPB4
AGS12	332 / RN7YC	AR32	14 / RJ12YC	ASF42C6	79 / RV15YC6	AYFS22FM	3017 / RES8PYB5	CYFS12F3	9016 / RES8WYCB5
AGS12C	332 / RN7YC	AR41	871 / RJ8C	ASF42C7	79 / RV15YC6	AYFS32YR	9901 / RE10WYPB5	CYFS12F5	3017 / RES8PYB5
AGS1C	880 / RN3C	AR42	14 / RJ12YC	ASF42P	3018 / RV17PMC4	AYSF32YPC	9901 / RE10WYPB5	CYFS12Y	3017 / RES8PYB5
AGS22C	415 / RN9YC	AR426	66 / RJ18YC6	ASF44P	3036 / RV17PZMC	AZ2	825 / J4C	CYFS12Y3	9016 / RES8WYCB5
AGS2C	104 / RN4C	AR4S	557 / XEJ8	ASF4C	121 / RV8C	AZ3	823 / J6C	CYFS12YEC	9016 / RES8WYCB5
AGS32C	404 / RN12YC	AR51	871 / RJ8C	ASF4C6	108 / RV8C6	AZ9	592 / RJ12C	CYFS12YPC	9016 / RES8WYCB5
AGS3C	123 / RN5C	AR52	63 / RJ14YC	ASF52	18 / RV15YC4	AZFS22FE	7437 / RE10PYPB5	CYFS12YPC	9016 / RES8WYCB5
AGS42C	404 / RN12YC	AR526	66 / RJ18YC6	ASF526	79 / RV15YC6	AZFS32FE	7437 / RE10PYPB5	ESD10	169 / CH69
AGS44	101 / RN13LYC	AR5S	588 / XMJ14	ASF52C	18 / RV15YC4	AZFS32FE	7981 / RE14PYPB4	EZD11	168 / CH68
AGS4C	123 / RN5C	AR6S	557 / XEJ8	ASF52C7	79 / RV15YC6	B2W	506 / D6	EZD14	168 / CH68
AGS52C	404 / RN12YC	AR7N	840 / RCJ8	ASF8	113 / RV12C	B3W	509 / D9	EZD15	163 / CH63
AGS52C6	105 / RN16YC5	AR7S	517 / XMJ17	ASF86	35 / RV12C6	B3X	509 / D9	EZD17	161 / CH61
AGSF2	304 / RS9YC	AR7X	871 / RJ8C	AT1	825 / J4C	B4X	509 / D9	EZD2	163 / CH63
AGSF22C	304 / RS9YC	AR80	511 / J11C	AT10	592 / RJ12C	B6W	514 / D14	EZD4	163 / CH63
AGSF22FCM	3066 / RS7PYB5	AR82	58 / RJ18YC	AT2	825 / J4C	B82	515 / D15Y	EZD5	168 / CH68
AGSF22FM	7963 / RS12PYPB5	AR826	66 / RJ18YC6	AT3	823 / J6C	B8X	516 / D16	F11	525 / 25
AGSF22FM1	3026 / RS7PYC	AR828	66 / RJ18YC6	AT4	823 / J6C	BF12	409 / RF9YC	HG2	809 / RA6HC
AGSF22FM1	3401 / RS10PYC4	AR8S	567 / XEJ12	AT42	10 / J12YC	BF22	409 / RF9YC	HG22C	809 / RA6HC
AGSF22PP	7401 / RS12PYP5	AR9S	573 / XMJ20	AT6	841 / J8C	BF32	409 / RF9YC	HGS22C	809 / RA6HC
AGSF22WM	9204 / RS12WYPB4	ARF2	802 / V63C	AT8	511 / J11C	BF42	22 / RF11YC	HJFS24FP	9406 / RET8ZWMPB4
AGSF22YPC	7963 / RS12PYPB5	ARF22	400 / RV9YC	ATL4	587 / H8C	BF42C	22 / RF11YC	HV2	816 / P7
AGSF23C	15 / RS15LYC	ARF26	802 / V63C	ATL8	844 / H10C	BF82	22 / RF11YC	HV22	888 / P8Y
AGSF24C	403 / RS10LC	ARF3	121 / RV8C	AV091X4	821 / L77JC4	BF82C	22 / RF11YC	HV3	888 / P8Y
AGSF24FM	7407 / RS14ZPYPB	ARF32	406 / RV12YC	AV1X	807 / L78C	BF92	22 / RF11YC	P6	842 / UY6
AGSF24N	403 / RS10LC	ARF326	79 / RV15YC6	AV2X	811 / L82C	BR4S	572 / XED14	PV2	808 / Z9Y
AGSF24N	9200 / RS10ZWYPB5	ARF32M	406 / RV12YC	AV4	306 / L86C	BR5S	649 / XMD15	PV3	808 / Z9Y
AGSF32C	401 / RS12YC	ARF36	108 / RV8C6	AV42	929 / RL95YC	BR7S	521 / XMD21	PV3F	808 / Z9Y
AGSF32FM	7940 / RS14PYPB5	ARF4	121 / RV8C	AV52	929 / RL95YC	BR8	541 / RD16	PZT1FF4	7989
AGSF32FM	7963 / RS12PYPB5	ARF42	406 / RV12YC	AV6	896 / L90C	BR8S	563 / XED16	SP506	7407 / RS14ZPYPB
AGSF32PM	7963 / RS12PYPB5	ARF426	79 / RV15YC6	AV82	929 / RL95YC	BR9S	521 / XMD21	TT10	569 / W14
AGSF32PM	9808 / RS8WYPB4	ARF46	108 / RV8C6	AVKO	827	BRF32	409 / RF9YC	TT15	589 / W89D
AGSF32PMF4	7963 / RS12PYPB5	ARF52	18 / RV15YC4	AVKOD	129 / RF10C	BRF3M	129 / RF10C	TT4	510 / W10
AGSF32PP	7401 / RS12PYP5	ARF526	79 / RV15YC6	AVR3S	612 / RML12	BRF42	22 / RF11YC	TT8	569 / W14
AGSF32WM	9808 / RS8WYPB5	ARF528	37 / RV17YC6	AVZKO	831 / UL77V	BRF82	22 / RF11YC	ZD1	180 / CH80
AGSF32YPC	7963 / RS12PYPB5	ARF6	113 / RV12C	AWRF325	13 / RS14YC6	BS5S	649 / XMD15	ZD13	194 / CH243
AGSF32YPC	9404 / RS14WYPB5	ARF62	25 / RV17YC	AWRF42	401 / RS12YC	BS9S	521 / XMD21	ZD8	184 / CH84
AGSF32YR	9404 / RS14WYPB5	ARF626	37 / RV17YC6	AWSF22C	304 / RS9YC	BSF3	129 / RF10C	ZD9	184 / CH84
AGSF33C	15 / RS15LYC	ARF8	113 / RV12C	AWSF22E	3401 / RS10PYC4	BSF31	129 / RF10C		
AGSF34C	403 / RS10LC	ARF86	35 / RV12C6	AWSF22EE	7401 / RS12PYP5	BSF314	129 / RF10C		
AGSF34EE	7407 / RS14ZPYPB	ARL4S	610 / REL88B	AWSF24	403 / RS10LC	BSF42	22 / RF11YC		
AGSF34FM	3024 / RS10ZPYC4	ARL5	587 / H8C	AWSF24C	403 / RS10LC	BSF42C	22 / RF11YC		
AGSF34FM	7407 / RS14ZPYPB	ARL6S	610 / REL88B	AWSF32	401 / RS12YC	BSF44C	130 / RF14LC		
AGSF42C6	13 / RS14YC6	ARL8	854 / RH10C	AWSF32C	401 / RS12YC	BSF6	129 / RF10C		
AGSF43C	15 / RS15LYC	ARL82	854 / RH10C	AWSF32E	3401 / RS10PYC4	BSF82	22 / RF11YC		
AGSF52C	408 / RS14YC	ARL8S	610 / REL88B	AWSF32EE	7401 / RS12PYP5	BSF82C	22 / RF11YC		
AGSP22C	71 / RC12YC	AS42C	14 / RJ12YC	AWSF32F	3401 / RS10PYC4	BSF92	22 / RF11YC		
AGSP32	71 / RC12YC	AS42C6	66 / RJ18YC6	AWSF32P	3401 / RS10PYC4	BT10	502 / D21		
AGSP32C	71 / RC12YC	AS4C	102 / RJ6C	AWSF32PP	7401 / RS12PYP5	BT15	543 / D89D		
AGSP32PP	7071 / RC12PYP	AS52C	63 / RJ14YC	AWSF34	403 / RS10LC	BT2	506 / D6		
AGSP33C	318 / RC12M4	AS5S	588 / XMJ14	AWSF34C	403 / RS10LC	BT3	509 / D9		
AGSP52	71 / RC12YC	AS6S	557 / XEJ8	AWSF34EE	7407 / RS14ZPYPB	BT4	509 / D9		
AGSP52C	71 / RC12YC	AS7S	517 / XMJ17	AWSF34PP	7407 / RS14ZPYPB	BT6	514 / D19		

**NGK**



**CROSS REFERENCE**  
**TABLEAU DE RENVOIS**  
**REFERENCIA CRUZADA**



**CAUTION. DO NOT USE THIS CHART**

UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.

**ATTENTION. NE PAS UTILISER CE TABLEAU**

SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.

**PRECAUCIÓN. NO USE ESTA TABLA**

A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

NGK	NGK	NGK	NGK	NGK					
APR5FS11	22 / RF11YC	BCPR5ES	71 / RC12YC	BP5EAL	302 / N11YC	BPR5EFVX	7401 / RS12PYP5	BR7EFS	344 / RC9YC
APR5FS15	22 / RF11YC	BCPR5ES11	71 / RC12YC	BP5EAL11	302 / N11YC	BPR5ES	322 / RN11YC4	BR7ES	880 / RN3C
APR6FS	409 / RF9YC	BCPR5EY	71 / RC12YC	BP5EFS	401 / RS12YC	BPR5ES	404 / RN12YC	BR7ES11	880 / RN3C
AR5FS	129 / RF10C	BCPR5EY11	71 / RC12YC	BP5EQ13	38 / N12YC	BPR5ES11	322 / RN11YC4	BR7HS	874 / RL82C
AR6FS	129 / RF10C	BCPR5EY11	71 / RC12YC	BP5ES	302 / N11YC	BPR5ES11	404 / RN12YC	BR7HS10	874 / RL82C
AR6FS11	129 / RF10C	BCPR6EVX11	3344 / RC9PYC	BP5ES11	302 / N11YC	BPR5EV	322 / RN11YC4	BR8EG	1026 / QC59
B10EG	693 / C55	BCPR7ER	71 / RC12YC	BP5EV	302 / N11YC	BPR5EY	5322	BR8ES	818 / RN2C
B10HS	821 / L77JC4	BKR4E	431 / RC14YC	BP5EY	302 / N11YC	BPR5EY	322EZ / 322EZ	BR8ESA	818 / RN2C
B2	592 / RJ12C	BKR4EVX	431 / RC14YC	BP5FS	18 / RV15YC4	BPR5EY	404 / RN12YC	BR8EV	818 / RN2C
B2LM	861 / J19LM	BKR5E	71 / RC12YC	BP5HA	929 / RL95YC	BPR5EY11	322 / RN11YC4	BR8HCS10	883 / QL78C
B2LMY	5861	BKR5E11	71 / RC12YC	BP5HS	929 / RL95YC	BPR5EY11	404 / RN12YC	BR8HS	883 / QL78C
B2LMY	861 / J19LM	BKR5EGP	3071 / RC12PYP	BP5S	322 / RJ14YC	BPR5FS11	18 / RV15YC4	BR8HS10	883 / QL78C
B2LMY	861EZ / 861EZ	BKR5EIX11	3071 / RC12PYP	BP6EFS	401 / RS12YC	BPR5HS	929 / RL95YC	BR8HV	883 / QL78C
B4ES	120 / N5C	BKR5EKB11	71 / RC12YC	BP6EK	300 / N9YC	BPR5S	63 / RJ14YC	BR9ECS	8902
B4H	896 / L90C	BKR5EKP11	7071 / RC12PYP	BP6EKA	300 / N9YC	BPR6EFS	401 / RS12YC	BR9EG	1025 / QC57
B4HS	896 / L90C	BKR5EQU	71 / RC12YC	BP6EQ13	322 / RN11YC4	BPR6EKA	415 / RN9YC	BR9ES	8902
B4L	844 / H10C	BKR5EN11	71 / RC12YC	BP6ES	300 / N9YC	BPR6EKN	332 / RN7YC	BR9ES	818 / RN2C
B4L	857 / RH18Y	BKR5EP11	7071 / RC12PYP	BP6ES11	300 / N9YC	BPR6ES	415 / RN9YC	BR9EYA	8902
B4LM	845 / J17LM	BKR5ES	71 / RC12YC	BP6ES13	322 / RN11YC4	BPR6ES11	415 / RN9YC	BR9HS	828
B4LMY	845 / J17LM	BKR5ES11	71 / RC12YC	BP6ET	300 / N9YC	BPR6EV	415 / RN9YC	BR9HS10	828
B5EB	120 / N5C	BKR5EY	71 / RC12YC	BP6EV	300 / N9YC	BPR6EY	415 / RN9YC	BU6EFSZ	304 / RS9YC
B5ES	120 / N5C	BKR5EY11	71 / RC12YC	BP6EY	300 / N9YC	BPR6EY11	415 / RN9YC	BU8ET	300 / N9YC
B5EV	120 / N5C	BKR5EYA	71 / RC12YC	BP6EY	300 / N9YC	BPR6EZ	415 / RN9YC	BU8H	885M / L6VC
B5HS	896 / L90C	BKR5EYA11	71 / RC12YC	BP6HS	406 / RV12YC	BPR6FS	406 / RV12YC	BUE	890 / N19V
B6EB	120 / N5C	BKR6E	71 / RC12YC	BP6HS10	312 / L87YC	BPR6FS11	406 / RV12YC	BUH	837 / L20V
B6EB11	120 / N5C	BKR6EK	71 / RC12YC	BP6S	10 / J12YC	BPR6HS	327 / RL87YC	BUHW	827
B6EBL11	415 / RN9YC	BKR6EKP11	7071 / RC12PYP	BP7EFS	304 / RS9YC	BPR6HS10	327 / RL87YC	BUHW2	833
B6ES	803 / N4C	BKR6EKUB	9800 / RC6WYPB4	BP7ES	813 / N7YC	BPR6HSA	327 / RL87YC	BUHX	837 / L20V
B6ES11	803 / N4C	BKR6EP11	7071 / RC12PYP	BP7ES11	813 / N7YC	BPR6S	14 / RJ12YC	BUHXW1	831 / UL77V
B6EV	803 / N4C	BKR6EPB11	7071 / RC12PYP	BP7EV	813 / N7YC	BPR7E	332 / RN7YC	BUR6EA11	415 / RN9YC
B6HS	306 / L86C	BKR6EQUA	353 / RC89TMC	BP7FS	400 / RV9YC	BPR7ES	332 / RN7YC	BUR6EB11	415 / RN9YC
B6HS10	306 / L86C	BKR6EQUP	353 / RC89TMC	BP7HS	328 / L82YC	BPR7ES11	332 / RN7YC	BUR7EA11	332 / RN7YC
B6HV	306 / L86C	BKR6ES	71 / RC12YC	BP7HS10	328 / L82YC	BPR7EY11	415 / RN9YC	BUR7EB11	332 / RN7YC
B6L	844 / H10C	BKR6ES11	71 / RC12YC	BP8ES	315 / N6YC	BPR7HS	814 / RL82YC	BUZ8H	886
B6LY	844 / H10C	BKR6EY	71 / RC12YC	BP8EV	315 / N6YC	BPR7HS10	814 / RL82YC	BUZ8H	886M / QL6VC
B6S	841 / J8C	BKR6EYA	3071 / RC12PYP	BP8HN10	936	BR8ES	339 / RN6YC	BUZHW	898 / QL76V
B6Y	5843	BKR6EYA	7071 / RC12PYP	BP8HS	936	BPR8HS15	939	BUZHW2	838
B6Y	841 / J8C	BKR6EYA	71 / RC12YC	BP8HS10	936	BPR9ES	937 / RN57YC	BZ7HS10	828
B6Y	843EZ / 843EZ	BKR6EYA	9201 / RC12WYPB4	BP8HS15	924	BPR9ES	954 / RN57YC	C7E	654 / G59C
B7EB	803 / N4C	BKR7EQUP	9800 / RC6WYPB4	BPMA	848 / CJ8Y	BPR28HN10	938M / QL78YC	C8E	654 / G59C
B7EB11	803 / N4C	BKR7ES11	340 / RC7YC	BPM6A	853 / CJ7Y	BPZ8HS10	938M / QL78YC	C9E	653 / G57C
B7EG	688 / C61	BM4A	5846	BPM6A10	853 / CJ7Y	BPZ8HS15	939	C9H	889 / Z6
B7ES	801 / N3C	BM4A	846 / CJ14	BPM6F	855 / DJ7Y	BR2LM	868 / RJ19LM	CM6	877 / Y82
B7ES11	801 / N3C	BM4A	846EZ / 846EZ	BPM6Y	853 / CJ7Y	BR4ES	123 / RN5C	CMR5H	965 / RZ7C
B7EV	801 / N3C	BM4Y	5846	BPM7	58 / RJ18YC	BR4HS	896 / L90C	CMR6A	978 / RY4C
B7HS	811 / L82C	BM4Y	846 / CJ14	BPM7A	858 / CJ6Y	BR4LM	856 / RJ17LM	CMR6H	965 / RZ7C
B7HS10	811 / L82C	BM4Y	846EZ / 846EZ	BPM7Y	858 / CJ6Y	BR527Y11	322 / RN11YC4	CMR7A	978 / RY4C
B7HV	811 / L82C	BM6A	5843	BPM8Y	858 / CJ6Y	BR529Y11	322 / RN11YC4	CMR7H	965 / RZ7C
B7S	823 / J6C	BM6A	843 / CJ8	BPMR4A	863 / RCJ8Y	BR5EB	123 / RN5C	CPR8E	977 / RG6YC
B8ECS	805 / N2C	BM6A	843EZ / 843EZ	BPMR4A10	863 / RCJ8Y	BR5EB11	123 / RN5C	CPR8EB	977 / RG6YC
B8EG	687 / C59	BM6F	847 / DJ8J	BPMR6A	859 / RCJ7Y	BR5ES	123 / RN5C	CPR8EB9	977 / RG6YC
B8ES	805 / N2C	BM6FY	847 / DJ8J	BPMR7A	852 / RCJ6Y	BR5ES11	123 / RN5C	CR6E	654 / G59C
B8EV	805 / N2C	BM6Y	5843	BPMR7Y	852 / RCJ6Y	BR5FS	113 / RV12C	CR7E	654 / G59C
B8FS	802 / V63C	BM6Y	843 / CJ8	BPMR8Y	852 / RCJ6Y	BR5HS	896 / L90C	CR8E	654 / G59C
B8HS	807 / L78C	BM6Y	843EZ / 843EZ	BPR2ES	405 / RN14YC	BR6E	123 / RN5C	CR9E	653 / G57C
B8HS10	807 / L78C	BM7	843 / CJ8	BPR2ES11	105 / RN16YC5	BR6EB11	123 / RN5C	CR9EB	349 / RC4PHP
B8HV	807 / L78C	BM7A	849 / CJ6	BPR4ES	405 / RN14YC	BR6EBL11	415 / RN9YC	CR9EB	654 / G59C
B8S	825 / J4C	BM7Y	849 / CJ6	BPR4ES11	405 / RN14YC	BR6ES	104 / RN4C	CR9EH9	8654
B9EG	686 / C57	BMR2A	846 / CJ14	BPR4EY	405 / RN14YC	BR6ES11	104 / RN4C	CR9EHIX9	8654
B9ES	805 / N2C	BMR4A	846 / CJ14	BPR4FS	18 / RV15YC4	BR6FS	400 / RV9YC	CR9EK	653 / G57C
B9FS	802 / V63C	BMR6A	840 / RCJ8	BPR4FS11	18 / RV15YC4	BR6FVX	3018 / RV17PMC4	CS1	861 / J19LM
B9HS	821 / L77JC4	BMR7A	849 / CJ6	BPR4HS	929 / RL95YC	BR6HS	830 / RL86C	CS2	843 / CJ8
B9HS10	821 / L77JC4	BP4ES	405 / RN14YC	BPR4HS10	929 / RL95YC	BR6HS10	830 / RL86C	CS3	841 / J8C
B9HV	821 / L77JC4	BP4H	929 / RL95YC	BPR4S15	58 / RJ18YC	BR6HS10	933M / QL86C	CS4	845 / J17LM
BCP5ES	71 / RC12YC	BP4HA	929 / RL95YC	BPR5EAL	322 / RN11YC4	BR6S	871 / RJ8C	CS5	846 / CJ14
BCP5EV	71 / RC12YC	BP4HS	929 / RL95YC	BPR5EAL11	322 / RN11YC4	BR7EB	104 / RN4C	CS6	71 / RC12YC
BCPR5E11	71 / RC12YC	BP4HS10	929 / RL95YC	BPR5EFS	401 / RS12YC	BR7EB11	104 / RN4C	D5HS	910 / P10Y
BCPR5EP8	7071 / RC12PYP	BP5EA	38 / N12YC	BPR5EFS10	401 / RS12YC	BR7EF	344 / RC9YC	D6EA	810 / RA8HC



**CAUTION. DO NOT USE THIS CHART**  
 UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.

**ATTENTION. NE PAS UTILISER CE TABLEAU**  
 SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.

**PRECAUTION. NO USE ESTA TABLA**

A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

NGK		NGK		NGK		NGK		PRESTOLITE		
D6HA	888 / P8Y	IJR7A9	8812	PFR6N11	7071 / RC12PYP	SILZKR7B1	9023 / RER10WMPB4	189	502 / D21	
D6HV	888 / P8Y	IJR7A9	7972 / RA8PHP	PFR6Q	7346 / RC10PYP4	SPLZFR5B13EG9055	REC12WMPB5	788	569 / W14	
D7EA	810 / RA8HC	ILFR6B	9030 / REC8WYPB3	PFR6Q	7546 / RC10PYPB4	TR4	15 / RS15LYC	1401	825 / J4C	
D7ES	810 / RA8HC	ILFR6G	9030 / REC8WYPB3	PFR6Q	7548 / KC10PYPB4	TR5	408 / RS14YC	1411	592 / RJ12C	
D7EV	810 / RA8HC	ILFR6J11K	9033 / REC8WYPB4	PFR6T10G	7546 / RC10PYPB4	TR51	13 / RS14Y06	1432	10 / J12YC	
D8EA	809 / RA6HC	ILFR6T11	9006 / REC10WYPB4	PFR6T10G	9802 / RC8WYPB4	TR51VX	7013 / RS14PYP5	1442	10 / J12YC	
D8EV	809 / RA6HC	ILTR5A13G	9901 / RE10WYPB5	PFR6U11G	7346 / RC10PYP4	TR55	13 / RS14Y06	1452	63 / RJ14YC	
D8HA	816 / P7	ILTR5K13	9901 / RE10WYPB5	PFR6WTG	9805 / KC8WYPB4	TR55VX	3013 / RS14PYC6	1482	58 / RJ18YC	
D8HV	816 / P7	ILTR6H8G	9016 / RES8WYCB5	PFR6X11	9805 / KC8WYPB4	TR5BP12	9204 / RS12WYPB4	1810	502 / D21	
D9EA	905 / RA4HC	ILZFR6D11	9044 / REC8WMPB4	PFR7G11S	9800 / RC6WYPB4	TR5C12	9204 / RS12WYPB4	1852	515 / D15Y	
DCPR6E	810 / RA8HC	ILZKR7B1S	9407 / RER8ZWYCB4	PFR7ND	7318 / RC12PMPB4	UR4	18 / RV15YC4	1882	549 / D18Y	
DCPR7E	810 / RA8HC	ILZKR7B1S	9407 / RER8ZWYCB4	PFR7S8EG	9770 / RC6WYPB3	UR5	406 / RV12YC	7810	569 / W14	
DCPR8E	809 / RA6HC	IMR9B9H	8654	PGR5C11	7332 / RN10PYP4	UR55	406 / RV12YC	56728	796 / C63YC	
DCPR8EKP	8809	ITR4A15	9404 / RS14WYPB5	PLFR4A11	9040 / REC14WYPB4	WR41	130 / RF14LC	12G2	809 / RA6HC	
DCPR9E	905 / RA4HC	ITR5F13	9204 / RS12WYPB4	PLFR5A11	7975 / REC10PYPB4	WR5	22 / RF11YC	12G3	809 / RA6HC	
DIFR5C11	9002 / RC10WMPB4	ITR6F13	9001 / RC10WYPB4	PLFR5A11	9006 / REC10WYPB4	XR4	58 / RJ18YC	1411N	846 / CJ14	
DIFR6C11	9806 / RC8WMPB4	IZFR5K	9000 / RC10ZWYPB4	PLFR6A11	7975 / REC10PYPB4	XR5	63 / RJ14YC	1411X	592 / RJ12C	
DILFR5A11	9775 / REC8WYPB4	IZFR5K11	9202 / RC12WMPB4	PLKRTA	7019 / KER8PYPB	YR5	113 / RV12C	142X	825 / J4C	
DILFR5A11D	9775 / REC8WYPB4	IZFR6F11	9809 / QC8WEP	PLZFR6A11S	9044 / REC8WMPB4	ZFR5AP	3720 / RC12PMC3	143N	849 / C16	
DIFR5C11	9006 / REC10WYPB4	IZFR6H11	9812 / RC8ZWYPB4	PLZKAR6A11	9410 / REA12WMPB4	ZFR5F	71 / RC12YC	143X	563 / J6C	
DILKAR7B11	9412 / REA9WYPB4	IZFR6J	9812 / RC8ZWYPB4	PLZTR5A13	7032 / RE10PMPB5	ZFR5F11	318 / RC12MC4	147N	843 / C18	
DILZKR7A11DS	9407 / RER8ZWYCB4	IZFR6K11	9014 / RC8ZWYPB	PTR5A13	7437 / RE10PYPB5	ZFR5F11	9202 / RC12WMPB4	147X	841 / J8C	
DILZKR7A11G	9407 / RER8ZWYCB4	IZFR6K11	9812 / RC8ZWYPB4	PZFR5D11	7318 / RC12PMPB4	ZFR5FGP	3071 / RC12PYC	149X	511 / J11C	
DP6EA9	810 / RA8HC	IZFR6K11S	9812 / RC8ZWYPB4	PZFR5F	7071 / RC12PYP	ZFR5LP13G	7034 / RC12PEPB5	14ER4	830 / RL86C	
DP7EA9	810 / RA8HC	IZFR6K13	9813 / RC8ZWYPB5	PZFR5F11	7071 / RC12PYP	ZFR5N	438 / RC12ECC	14ER6	830 / RL86C	
DP7EV9	810 / RA8HC	IZFR6KL	9812 / RC8ZWYPB4	PZFR5J11	9782 / RC8ZWYPB4	ZFR6BPG	9812 / RC8ZWYPB4	14F22	400 / RV9YC	
DP8EA9	809 / RA6HC	IZKR7B	9702 / KA7ZWYPB4	PZFR6F11	7071 / RC12PYP	ZFR6F11G	9002 / RC10WMPB4	14F32	406 / RV12YC	
DP8EV9	809 / RA6HC	KR8AI	809 / RA6HC	PZFR6J11	9800 / RC6WYPB4	ZFR6K11	7318 / RC12PMPB4	14F3N	851 / DJ6J	
DPR6EA9	810 / RA8HC	LFR5A11	975 / REC10YC4	PZFR7G	9803 / RC8WMPB4	ZFR6J9	9013 / RC10WMB3	14F42	18 / RV15YC4	
DPR6EB9	810 / RA8HC	LFR5AGP	7975 / REC10PYPB4	PZNR6A11H	7406 / RET9ZWMPB4	ZFR6VG	434 / RC9MC4	14F52	18 / RV15YC4	
DPR7EA9	810 / RA8HC	LFR5A11X1	9006 / REC10WYPB4	PZTR5A15	7983 / RS14PMPB5	ZFR7F11	9803 / RC8WMPB4	14F7N	847 / DJ8J	
DPRT7EIX9	8810	LFR6A11	975 / REC10YC4	R0045J10	7070 / G54V	ZGR5C	101 / RN13LYC	14G01	789 / N19V	
DPR7EV9	810 / RA8HC	LFR6A11X1	7975 / REC10PYPB4	R01610	657 / G55R	<b>NISSAN</b>				
DPR8EA9	809 / RA6HC	LFR6A11X1	9033 / REC8WYPB4	R01611	656 / G53R	224011LA1C	9412 / REA9WYPB4	14G1	801 / N3C	
DPR8EV9	809 / RA6HC	LFR6C11	975 / REC10YC4	R01710	652 / G55C	2240127N66	7071 / RC12PYP	14G12	315 / N6YC	
DR4HS	910 / P10Y	LTR5GP	7437 / RE10PYPB5	R01710	653 / G57C	2240127N66	7071 / RC12PYP	14G2	803 / N4C	
DR5HS	910 / P10Y	LTR5IX11	9901 / RE10WYPB5	R0179	654 / G59C	2240150Y05	71 / RC12YC	14G22	300 / N9YC	
DR6HS	888 / P8Y	LTR6P13	3017 / RES8PYPB5	R0373A9	654 / G59C	2240150Y05	71 / RC12YC	14G3	120 / N5C	
DR7EA	810 / RA8HC	LTR6P13	3017 / RES8PYPB5	R21610	667 / A57R	2240150Y05	71 / RC12YC	14G32	302 / N11YC	
DR7ES	810 / RA8HC	LTR6P13	3017 / RES8PYPB5	R21710	661 / A57C	2240155Y15	71 / RC12YC	14G4	120 / N5C	
DR8EA	809 / RA6HC	LZFR5C11	446 / REC12MCC4	R56705	10 / J12YC	2240155Y15	71 / RC12YC	14G42	38 / N12YC	
DR8ES	809 / RA6HC	LZFR6A1	7975 / REC10PYPB4	R56705	10 / J12YC	22401CK81B	9410 / REA12WMPB4	14G5	120 / N5C	
DR8ESL	809 / RA6HC	LZKR7B11S	9407 / RER8ZWYCB4	R56707	266 / J63Y	22401EW61C	9412 / REA9WYPB4	14G52	405 / RN14YC	
FR4	71 / RC12YC	LZTR5A13	3032 / RE10PMC5	R56719	785 / C61C	22401JA01B	9410 / REA12WMPB4	14G7	120 / N5C	
FR5	431 / RC14YC	LZTR5A13	3032 / RE10PMC5	R5671A10	686 / C57	22401ZE01B	9775 / REC8WYPB4	14G82	405 / RN14YC	
FR5AP10	71 / RC12YC	LZTR5AGP	3032 / RE10PMC5	R5671A8	688 / C61	22401ZJ51B	9775 / REC8WYPB4	14G902	805 / N2C	
FR5AP11	3346 / RC10PYP	LZTR5AIX13	3032 / RE10PMC5	R5671A9	687 / C59	B2401F4103	71 / RC12YC	14G92	408 / RS14YC	
FR5AP11	9003 / RC10WYPB4	PFR5B11	7071 / RC12PYP	R567210	791 / C57YC	B2401F4103	71 / RC12YC	14GF22	82 / RFN14LY	
FR6AP10	346 / RC10YC4	PFR5B11B	7071 / RC12PYP	R56728	315 / N6YC	<b>POLARIS INDUSTRIES I</b>				
FR6EI	9801 / RC8WYPB3	PFR5C11	7071 / RC12PYP	R56729	792 / C59YC	2873084	7972 / RA8PHP	14GR22	415 / RN9YC	
GR4	322 / RN11YC4	PFR5G11	7071 / RC12PYP	R56729	794 / C61YC	3022111	990 / REA6MC	14GR32	322 / RN11YC4	
GR45	405 / RN14YC	PFR5G11E	7071 / RC12PYP	R56730	668 / V55C	3022274	992 / RG4YCX	14GR4	123 / RN5C	
IFR5G11	9001 / RC10WYPB4	PFR5J11	7071 / RC12PYP	R567310	669 / V57C	3022462	992 / RG4YCX	14GR42	404 / RN12YC	
IFR5G11	9003 / RC10WYPB4	PFR5L11	7071 / RC12PYP	R56737	263 / V61	3070190	954 / RN57YCC	14GR52	105 / RN16YC5	
IFR5J11	9003 / RC10WYPB4	PFR5N11	3346 / RC10PYP	R56737	802 / V63C	<b>PORSCHE</b>			14GR52	405 / RN14YC
IFR6A11	9202 / RC12WMPB4	PFR5N11	346 / RC10YC4	R56739	670 / V59C	95517021990	9702 / KA7ZWYPB4	14GR526	105 / RN16YC5	
IFR6A11	9806 / RC8WMPB4	PFR5N11	7071 / RC12PYP	R56740	671 / V57YC	<b>PORSCHE</b>			14GR52A	105 / RN16YC5
IFR6BK	9801 / RC8WYPB3	PFR5N11	7546 / RC10PYPB4	R56748	265 / V63Y	95517021990	9702 / KA7ZWYPB4	14GR53	101 / RN13LYC	
IFR6BK	9802 / RC8WYPB4	PFR5N11	9001 / RC10WYPB4	R56748	265 / V63Y	99917022390	9800 / RC6WYPB4	14GR7	123 / RN5C	
IFR6D10	9805 / KC8WYPB4	PFR6A11	7071 / RC12PYP	R568610	693 / C55	99917022890	9030 / REC8WYPB3	14GRF22	408 / RS14YC	
IFR6E11	9201 / RC12WYPB4	PFR6B	7071 / RC12PYP	R56868	688 / C61	<b>PRESTOLITE</b>			14GRF32	408 / RS14YC
IFR6J11	9201 / RC12WYPB4	PFR6B11	7071 / RC12PYP	R56869	687 / C59	143	823 / J6C	14GRF52	408 / RS14YC	
IFR6J11	9801 / RC8WYPB3	PFR6G11	7346 / RC10PYP4	R572410	684 / S57YC	144	841 / J8C	14L4	587 / H8C	
IFR6T11	9806 / RC8WMPB4	PFR6G11	7546 / RC10PYPB4	R57249	685 / S59YC	145	841 / J8C	14L7	844 / H10C	
IFR7F8DS	9770 / RC6WYPB3	PFR6G13	7071 / RC12PYP	R6918B9	1008 / QC59C	147	841 / J8C	14L9	512 / H12	
		PFR6H10	7346 / RC10PYP4	R6918C9	1008 / QC59C	149	511 / J11C	14R3	102 / RJ6C	
		PFR6J11	7071 / RC12PYP	SILFR6A	9030 / REC8WYPB3	183	509 / D9	14R32	14 / RJ12YC	
		PFR6L11	7071 / RC12PYP	SILFR6A	9030 / REC8WYPB3	184	509 / D9	14R4	871 / RJ8C	
		PFR6L13	7071 / RC12PYP	SILKAAAR7G11	9035 / REA11WMPB4	188	516 / D16	14R42	14 / RJ12YC	
				SILTR6A7G	9016 / RES8WYCB5			14R42	66 / RJ18YC6	



**CROSS REFERENCE**  
**TABLEAU DE RENVOIS**  
**REFERENCIA CRUZADA**



**CAUTION. DO NOT USE THIS CHART**

UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.

**ATTENTION. NE PAS UTILISER CE TABLEAU**

SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.

**PRECAUCIÓN. NO USE ESTA TABLA**

A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

PRESTOLITE		SILVER STREAK		SPLITFIRE		STITT		TORCH	
14R426	66 / RJ18YC6	773211	306 / L86C	SM8E	14 / RJ12YC	R80L	643 / RB75N	A8TC	889 / Z6
14R42A	66 / RJ18YC6	773231	805 / N2C	<b>STITT</b>		R817L	576 / RB76N	C6RTC	816 / P7
14R5	871 / RJ8C	773241	859 / RCJ7Y	10	510 / W10	R817L	643 / RB75N	C6TC	816 / P7
14R52	63 / RJ14YC	<b>SPLITFIRE</b>		13	510 / W10	R847	526 / RD15Y	D7CA	809 / RA6HC
14R52	66 / RJ18YC6	SF10D	401 / RS12YC	19	513 / C97B	R847	541 / RD16	D7RC	809 / RA6HC
14R526	66 / RJ18YC6	SF10D6	13 / RS14YC6	79	518 / W18	RE72	559 / RW83F	D7RTC	810 / RA8HC
14R52A	66 / RJ18YC6	SF14E	121 / RV8C	82	506 / D6	RF407L	406 / RV12YC	D7TC	810 / RA8HC
14R7N	840 / RCJ8	SF21F	844 / H10C	82	509 / D9	S2SGA105	578 / REW82P	D8C	905 / RA4HC
14R8	871 / RJ8C	SF254F	407 / RS14LC	82	514 / D14	S2SGA40L	551 / RHL79G	D8RC	809 / RA6HC
14RF22	400 / RV9YC	SF259D	801 / N3C	82	515 / D15Y	S2SGA40L	637 / RHL89G	D8RTC	809 / RA6HC
14RF32	406 / RV12YC	SF25E	843 / CJ8	82	516 / D16	S2SGA40L5	610 / REL88B	D8TC	809 / RA6HC
14RF32	79 / RV15YC6	SF263D	821 / L77JC4	82	549 / D18Y	DK7RTC	575 / RHN79G	DK7RTC	809 / RA6HC
14RF326	79 / RV15YC6	SF265F	306 / L86C	82	564 / D16J	S2SGA80	585 / RHM85G	E4RTC	929 / RL95YC
14RF32A	79 / RV15YC6	SF295F	847 / DJ8J	82	625 / D78Y	S2SGA805	503 / REM84P	E4TC	929 / RL95YC
14RF42	18 / RV15YC4	SF29E	841 / J8C	86	502 / D21	S405MC	557 / XEJ8	E5RTC	929 / RL95YC
14RF42	79 / RV15YC6	SF2C	400 / RV9YC	86	523 / D23	S40L5MC	522 / REL89G	E5TC	929 / RL95YC
14RF426	79 / RV15YC6	SF2D	406 / RV12YC	107	580 / W80N	S475MC	567 / XEJ12	E6C	830 / RL86C
14RF42A	79 / RV15YC6	SF2D6	79 / RV15YC6	117	580 / W80N	S47XL5MC	614 / XEN14	E6RC	830 / RL86C
14RF52	25 / RV17YC	SF2E	18 / RV15YC4	197	520 / W20	S825	550 / ED14	E6RTC	814 / RL82YC
14RF52	37 / RV17YC6	SF2E6	79 / RV15YC6	719	518 / W18	S825	572 / XED14	E6TC	312 / L87YC
14RF526	37 / RV17YC6	SF30C	102 / RJ6C	727	539 / W77N	S8275	568 / REM77N	E7RTC	814 / RL82YC
14RF528	37 / RV17YC6	SF392D	71 / RC12YC	827	566 / M82N	S865	563 / XED16	E7TC	814 / RL82YC
14RF52A	37 / RV17YC6	SF392D6	89 / RC12YC5	847	566 / M82N	S8MEX5	505 / ED89D	E8C	807 / L78C
14RF62	17 / RV19YC6	SF405C	805 / N2C	897	529 / D14N	SE722	544 / HH83F	E8RC	807 / L78C
14RF62	25 / RV17YC	SF405D	801 / N3C	912	589 / W89D	SR1072	532 / RHW80N	E8RTC	936
14RF626	17 / RV19YC6	SF405F	803 / N4C	137BSP	545 / W85N	SR137	579 / RHW79N	E8TC	936
14RF62A	17 / RV19YC6	SF409B	807 / L78C	137BSP	561 / W16Y	SR1375	534 / REW80N	F4RTC	405 / RN14YC
14RL4	587 / H8C	SF409C	811 / L82C	147B	569 / W14	SR7172	577 / RHW77N	F5RF	322 / RN11YC4
14RL7	854 / RH10C	SF40D	104 / RN4C	15E	525 / 25	SR7172	635 / RHW78N	F5RTC	322 / RN11YC4
14WRF24	403 / RS10LC	SF412C	814 / RL82YC	15EX	525 / 25	SR807	596 / RHM77N	F5RTC	404 / RN12YC
14WRF34	403 / RS10LC	SF413B	905 / RA4HC	17E	513 / C97B	SR817L	624 / RHB81N	F5TC	302 / N11YC
14WRF44	407 / RS14LC	SF415B	905 / RA4HC	17E	562 / W95D	SR827	583 / RHM83N	F5TC	404 / RN12YC
14WRF54	407 / RS14LC	SF415C	809 / RA6HC	17E	589 / W89D	U827	541 / RD16	F6RF	415 / RN9YC
18F3	129 / RF10C	SF416B	905 / RA4HC	17E	595 / C95F	<b>SUBARU</b>		F6RTC	415 / RN9YC
18F32	409 / RF9YC	SF416C	809 / RA6HC	17EX	513 / C97B	22401AA630	9006 / REC10WYPB4	F6TC	300 / N9YC
18F42	22 / RF11YC	SF416D	810 / RA8HC	17EX	562 / W95D	22401AA650	9003 / RC10WYPB4	F6TC	415 / RN9YC
18F6	21 / RF14YC	SF425C	300 / N9YC	17EX	589 / W89D	22401AA65A	9003 / RC10WYPB4	F7C	123 / RN5C
18F82	21 / RF14YC	SF426C	322 / RN11YC4	17EX	595 / C95F	22401AA670	7975 / REC10PYPB4	F7RTC	332 / RN7YC
18RF3	129 / RF10C	SF426E	404 / RN12YC	2SGA10	582 / RW82P	22401AA670	9030 / REC8WYPB3	F7RTC	332 / RN7YC
18RF32	409 / RF9YC	SF45F	845 / J17LM	2SGA40XL	530 / RTN79G	22401AA780	9035 / REA11WMPB4	F7TC	332 / RN7YC
18RF42	22 / RF11YC	SF4E	22 / RF11YC	2SGA80	591 / RM85G	<b>SUZUKI</b>		F7TJC	332 / RN7YC
18RF82	21 / RF14YC	SF512E	130 / RF14LC	407L	102 / RJ6C	948200549	9003 / RC10WYPB4	F8C	104 / RN4C
CR56869	686 / C57	SF514D	407 / RS14LC	407XL	430 / RC9YC4	1118282200	9006 / REC10WYPB4	F8RC	104 / RN4C
<b>SAAB</b>		SF516D	15 / RS15LYC	817L	542 / B86N	1118282210	9775 / REC8WYPB4	F8RTC	315 / N6YC
55571391	7348 / KC11PYP	SF522D	71 / RC12YC	8ME	543 / D89D	<b>TORCH</b>		F8TC	315 / N6YC
55571391	9802 / RC8WYPB4	SF524E	15 / RS15LYC	8ME	597 / K97F	8001	3071 / RC12PYC	G4C	592 / RJ12C
<b>SILVER STREAK</b>		SF5C	300 / N9YC	8MEX	543 / D89D	8002	3071 / RC12PYC	G6C	841 / J8C
773001	853 / CJ7Y	SF6C	415 / RN9YC	8MEX	597 / K97F	8003	3401 / RS10PYC4	G6RC	511 / J11C
773011	861 / J19LM	SF6D	322 / RN11YC4	CP107	554 / RGC80N	8004	415 / RN9YC	GL4	845 / J17LM
773021	843 / CJ8	SF6E	404 / RN12YC	CP717	552 / RGC77N	8005	15 / RS15LYC	GL4C	861 / J19LM
773031	71 / RC12YC	SF6F6	105 / RN16YC5	CPE72	623 / RGC80F	8006	3401 / RS10PYC4	GL4RC	868 / RJ19LM
773041	847 / DJ8J	SF8E	14 / RJ12YC	CPM10	638 / RTW80N	8007	3071 / RC12PYC	K4RTC3	71 / RC12YC
773051	868 / RJ19LM	SF8E6	66 / RJ18YC6	CPM2SGA40L	556 / RTL85G	8008	404 / RN12YC	K5RF11	71 / RC12YC
773061	840 / RCJ8	SF8G6	66 / RJ18YC6	CPM2SGA40XL	540 / RTN79G	8010	332 / RN7YC	K5RTC	71 / RC12YC
773071	852 / RCJ6Y	SF98E	412 / RC12LYC	CPM80	548 / RTM79	8012	304 / RS9YC	K5RTC11	71 / RC12YC
773081	849 / CJ6	SM10D	401 / RS12YC	CPM807	547 / RTM77N	8013	3071 / RC12PYC	K5TC	302 / N11YC
773091	848 / CJ8Y	SM14E	121 / RV8C	CPM80L	646 / RTB80N	9001	7401 / RS12PYP5	K6RF11	430 / RC9YC4
773101	302 / N11YC	SM21F	844 / H10C	CPR887	586 / RGM86N	9002	7401 / RS12PYP5	K6RTC11	430 / RC9YC4
773111	858 / CJ6Y	SM264D	821 / L77JC4	E84	571 / RM79F	9003	15 / RS15LYC	K6RTC	430 / RC9YC4
773121	415 / RN9YC	SM29E	841 / J8C	R107	553 / RW80N	9004	7401 / RS12PYP5	K6TC	430 / RC9YC4
773131	845 / J17LM	SM2C	400 / RV9YC	R2SGA40L	620 / RL85G	9005	7071 / RC12PYP	K6TJC	430 / RC9YC4
773141	322 / RN11YC4	SM2D	406 / RV12YC	R407L	535 / RL15B	9006	7071 / RC12PYP	K7RTC	430 / RC9YC4
773151	300 / N9YC	SM2E	18 / RV15YC4	R407XLC	218 / RC78PYP	9007	404 / RN12YC	K7TC	430 / RC9YC4
773161	851 / DJ6J	SM30C	102 / RJ6C	R40L	535 / RL15B	9009	332 / RN7YC	L6C	843 / CJ8
773171	841 / J8C	SM40D	104 / RN4C	R45	644 / RJ88P	A6RTC	889 / Z6	L6RC	843 / CJ8
773181	855 / DJ7Y	SM4E	22 / RF11YC	R717	565 / RW77N	A6TC	889 / Z6	L6RTC	848 / CJ8Y
773191	863 / RCJ8Y	SM6C	415 / RN9YC	R717	631 / RW78N	A7RTC	889 / Z6	L6RTC	863 / RCJ8Y
773201	929 / RL95YC	SM6E	404 / RN12YC	R807	519 / RM77N	A8RTC	889 / Z6	L6TC	848 / CJ8Y



**CAUTION. DO NOT USE THIS CHART**  
 UNLESS YOU ARE UNABLE TO FIND YOUR VEHICLE OR EQUIPMENT LISTED IN THE APPLICATION SECTIONS OF THE CHAMPION MASTER CATALOG.  
**ATTENTION. NE PAS UTILISER CE TABLEAU**  
 SAUF SI LE VÉHICULE OU L'ÉQUIPEMENT NE SE TROUVE PAS DANS LES SECTIONS DES APPLICATIONS DE CE CATALOGUE.  
**PRECAUCIÓN. NO USE ESTA TABLA**  
 A MENOS QUE NO PUEDA ENCONTRAR SU VEHÍCULO O EQUIPO INDICADO EN LAS SECCIONES DE APLICACIÓN DEL CATÁLOGO PRINCIPAL DE CHAMPION

**TORCH**

L7RTC	852 / RCJ6Y
L7RTC	858 / CJ6Y
L7TC	858 / CJ6Y
N6C	847 / DJ8J
N6RC	847 / DJ8J
N6RTC	855 / DJ7Y
N6TC	855 / DJ7Y
N7C	850 / DJ7J
N7RC	850 / DJ7J
P5RTC	406 / RV12YC
P5TC	406 / RV12YC
P6RTC	400 / RV9YC
P6TC	400 / RV9YC
P7RTC	400 / RV9YC
P7TC	400 / RV9YC
Q5RTC	401 / RS12YC
Q5TC	401 / RS12YC
Q6RTC	304 / RS9YC
Q6TC	304 / RS9YC
T5RTC	406 / RV12YC
T5TC	406 / RV12YC
T6RTC	22 / RF11YC
T6TC	22 / RF11YC

**TORO**

801254	863 / RCJ8Y
--------	-------------

**TOYOTA**

9008091180	9806 / RC8WMPB4
9008091181	9202 / RC12WMPB4
9008091181	9806 / RC8WMPB4
9008091184	9001 / RC10WYPB4
9091901176	318 / RC12MC4
9091901191	9033 / REC8WYPB4
9091901233	9806 / RC8WMPB4
9091901235	9033 / REC8WYPB4
9091901235	975 / REC10YC4
9091901237	9806 / RC8WMPB4
9091901240	9001 / RC10WYPB4
9091901247	9033 / REC8WYPB4
9091901253	9412 / REA9WYPB4
90919A1002	9033 / REC8WYPB4
90919A1003	9006 / REC10WYPB4

**VOLVO**

86920710	3071 / RC12PYC
86920720	3071 / RC12PYC

**VOLVO-PENTA MARINE**

875803	18 / RV15YC4
3851857	401 / RS12YC
3851859	18 / RV15YC4
3851861	18 / RV15YC4
3851868	18 / RV15YC4
3854399	401 / RS12YC
3856759	401 / RS12YC
3858996	7401 / RS12PYP5
3858997	7401 / RS12PYP5
3861632	7401 / RS12PYP5

**VW**

101905616	353 / RC89TMC
409059994	302 / N11YC
06H905601A	9770 / RC6WYPB3
06H905611	9770 / RC6WYPB3
101905600A	9800 / RC6WYPB4
101905600C	9782 / RC8ZWYPB4
101905601F	9782 / RC8ZWYPB4
101905606A	9702 / KA7ZWYPB4
101905611A	9805 / KC8WYPB4
101905621B	9805 / KC8WYPB4
101905631G	9770 / RC6WYPB3
101905631H	9770 / RC6WYPB3